

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI23003981/SQY3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP006311	
<b>Claimant Vehicle No :</b>	SHB4946P	<b>Insured Vehicle No :</b>	GBE5902P	
Date of Loss:	15/04/2023	Nature of Claim:	TP	Claim No: M2302472

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHB4946P</b>	Engine No:	2ZR2G10723
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU003090408
Reg. Date:	14/01/2020 (Man. Year: 2019)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R95	Rear Tyre Size:	195/65 R95
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,023.72	1,023.72	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,400.00	1,050.00	350.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,434.72</b>	<b>2,084.72</b>	<b>350.00</b>	<b>14.38</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,650.00</b>		
<b>(S\$)</b>	2,434.72	1,650.00	784.72	32.23
<b>+ GST 8.00/8.00% (S\$)</b>	194.78	132.00	62.78	32.23
<b>Nett Amount (S\$)</b>	<b>2,629.50</b>	<b>1,782.00</b>	<b>847.50</b>	<b>32.23</b>

**INSPECTION**

Date of Assignment:	18/04/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	17/04/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB4946P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR ASSY RH	Buckled	1,258.30 FL	*1,258.30 FL
2	1		*REAR DOOR APPS LOGO RH	Necessary	80.00 F	*80.00 F
F=Franchise part. L=ListItemDisc.						
					Sub Total (S\$)	1,338.30
					- List Item Discount on L Items 25.00/25.00% (S\$)	314.58
					Total Parts (S\$)	1,023.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	350.00
2	SPRAYPAINT	New	600.00	500.00
3	ADVERTISEMENT LOGO - DOOR	New	100.00	100.00
4	ADVERTISEMENT LOGO -FENDER REAR	New	100.00	100.00
Gross Labour Cost (\$\$)			1,400.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >