

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts: 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHD3005B/17/04/2023 15:29	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER COVER	20.00	0.00	tu ✓ *1,052.20 FL
2	1		*FRT BUMPER CLIPS	20.00	0.00	uq ✓ *22.00 FL
3	1		*RADIATOR GRILLE	20.00	0.00	X *1,480.00 FL
4	1		*HEADLAMP LH	20.00	0.00	cut ✓ *1,388.00 FL
5	1		*FRT BUMPER TOP BRACKET LH	20.00	0.00	uq ✓ *44.80 FL
6	1		*FRT BUMPER SIDE BRACKET LH	20.00	0.00	de ✓ *24.60 FL
7	1		*HEADLAMP SUPPORT PANEL ASSY	20.00	0.00	unx ✓ *907.40 FL
8	1		*FRT BUMPER GRILLE LH	20.00	0.00	unx ✓ *126.20 FL
9	1		*FRT FENDER LH	20.00	0.00	b/ ✓ *663.00 FL
10	1		*FRT FENDER SHIELD LH	20.00	0.00	unx ✓ *174.90 FL

F=Franchise part. L=ListItemDisc.

Supp \$222.60
Radiator top cover

Sub Total (S\$) 5,883.10

- List Item Discount on L Items (S\$) 1,176.62

Total Parts (S\$) 4,706.48

ComfortDelGro Engineering Pte Ltd/SHD3005B/17/04/2023 15:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

3372.40
20% 2697.92

/23, 3:29 PM

REF:

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 CHL ALL LIGHTING

New

30

60.00

2 TUFF KOTE

New

30

80.00

3 PANEL BEATING

New

350

600.00

4 SPRAY PAINTING CHARGE

New

500

600.00

Gross Labour Cost (S\$)

910

1,340.00

ComfortDelGro Engineering Pte Ltd/SHD3005B/17/04/2023 15:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2697.92

11

910

3618.92

4592900

2 days

Tanglin 92495717

WP 18/4/23 0345

cls resurvey after repair

Tanglin C/Khantawon

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: