

C

Kenneth

1074

The U/C / Chassis frame / Body Structure affected due to collision.

D.O.I. 2/5/2023

成 輝 摩 哆
SENG HWEE MOTOR

Block 1018 Yishun Industrial Park A

#01-350 Singapore 768760

Tel: 6755 5205 Fax: 6753 4407

Email: senghweemotor@gmail.com

Business Reg. No.: 228612/00D

Our Ref: 4028/23-3

Date: 02-05-2023

Your Ref:

Policy No:

Re: Estimate to Mit FUSO Lorry YN8391 Z

1. 1 pc Rear Side panel 4/11 B1 ✓ 800.00 ✓ 10%
2. Labour charges for Knocking, Welding
Work, remove & refit new parts. & painting 4,600.00 ✓ 550

TOTAL: \$ 1,400.00

Not witheld
1/1mp & 1000h
After Paint

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SENG HWEE MOTOR