



# Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-60, Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

## PARTICULARS OF CLAIM

|                               |                                     |                       |                   |
|-------------------------------|-------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (Own Damage)                     | Ref. No:              |                   |
| Policy No:                    | SP2003732344                        | Date of Loss:         | 12/04/2023        |
| Vehicle Reg. No.:             | YP1225G                             | Driveable?            |                   |
| Driver Age/Info:              | / MALE                              | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                  | Third Party Involved? | YES               |
| Insured/Claimant:             | SINGMAR MARINE AND OFFSHORE PTE LTD | Contact No:           | +6590213092       |
| Driver:                       | KANNAPPAN VIJAYAKUMAR               |                       |                   |
| Make/Model:                   | ISUZU NHR85AUE4A, 3.0 D (M)         | Vehicle Reg. Date:    | 15/01/2016        |
| Vehicle Colour:               | White                               |                       |                   |
| Engine No:                    | 4JJ12F9252                          | Chassis No:           | JAANHR85EF7100464 |
| Odometer:                     | 0 KM                                |                       |                   |
| Paint Type:                   |                                     |                       |                   |
| Total Loss?                   | NO                                  |                       |                   |
| Est. Duration of Repair (day) | 1                                   |                       |                   |
| Present Location:             | CHENG AUTO BODYWORKS (HQ)           |                       |                   |

## COST OF CLAIMS

|                              | Amount    |
|------------------------------|-----------|
| Parts                        | 39,651.70 |
| Miscellaneous Items          | 1,010.00  |
| Labour                       | 4,960.00  |
| Paintwork Labour             | 0.00      |
| Towing                       | 0.00      |
| Calculated Gross Total (S\$) | 45,621.70 |
| - Excess (S\$)               | 700.00    |
| (S\$)                        | 44,921.70 |
| + GST 8.00% (S\$)            | 3,593.74  |
| Nett Amount (S\$)            | 48,515.44 |

Tan Jia Wen 97475749 / 62563561  
Not Authorise 1 Ex \$700  
L/S Resurvey after repair  
Tan Jia Wen 1/1/2023  
20 days

This claim is handled by: LAI JIA WEN RACHEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 18 Apr 2023)

**Parts:** N/A ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Cheng Auto Bodyworks/YP1225G/18/04/2023 09:08

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

*C/S*

### Estimates on Parts

| No. | Qty | Part No. | Particulars               | %Disc | %Depr | Amount          |
|-----|-----|----------|---------------------------|-------|-------|-----------------|
| 1   | 1   | NA       | *ROOF PANEL               | 0.00  | 0.00  | Rx *950.00 F    |
| 2   | 1   | NA       | *A PILLAR RH              | 0.00  | 0.00  | bt *450.00 F    |
| 3   | 1   | NA       | *A PILLAR LH              | 0.00  | 0.00  | bt *450.00 F    |
| 4   | 1   | NA       | *WINDSCREEN               | 0.00  | 0.00  | cur *1,458.00 F |
| 5   | 1   | NA       | *WINDSCREEN MOULDING      | 0.00  | 0.00  | cur *206.00 F   |
| 6   | 1   | NA       | *DASHBOARD ASSY           | 0.00  | 0.00  | ? *791.00 F     |
| 7   | 1   | NA       | *AIRCON BLOWER ASSY       | 0.00  | 0.00  | ? *550.00 F     |
| 8   | 1   | NA       | *AIRCON EVAPORATER ASSY   | 0.00  | 0.00  | ? *1,350.00 F   |
| 9   | 1   | NA       | *DOOR RH                  | 0.00  | 0.00  | bt *750.00 F    |
| 10  | 1   | NA       | *DOOR LH                  | 0.00  | 0.00  | bt *750.00 F    |
| 11  | 1   | NA       | *DOOR HINGE UPPER LH      | 0.00  | 0.00  | bt *45.00 F     |
| 12  | 1   | NA       | *DOOR HINGE LOWER LH      | 0.00  | 0.00  | bt *45.00 F     |
| 13  | 1   | NA       | *DOOR HINGE UPPER RH      | 0.00  | 0.00  | bt *45.00 F     |
| 14  | 1   | NA       | *DOOR HINGE LOWER RH      | 0.00  | 0.00  | bt *45.00 F     |
| 15  | 1   | NA       | *DOOR RUBBER RH           | 0.00  | 0.00  | cut *70.00 F    |
| 16  | 1   | NA       | *DOOR RUBBER LH           | 0.00  | 0.00  | cut *70.00 F    |
| 17  | 1   | NA       | *REAR CABIN PANEL         | 0.00  | 0.00  | Rx *1,450.00 F  |
| 18  | 1   | NA       | *CABIN FLOOR PANEL        | 0.00  | 0.00  | ? *1,200.00 F   |
| 19  | 1   | NA       | *OUTER CENTRE PANEL       | 0.00  | 0.00  | bt *462.00 F    |
| 20  | 1   | NA       | *INNER CENTRE PANEL       | 0.00  | 0.00  | bt *673.00 F    |
| 21  | 1   | NA       | *GRILLE ASSY              | 0.00  | 0.00  | cur *316.00 F   |
| 22  | 1   | NA       | *ISUZU EMBLEM             | 0.00  | 0.00  | cur *118.00 F   |
| 23  | 1   | NA       | *CORNER SIDE PANEL RH     | 0.00  | 0.00  | cur *194.00 F   |
| 24  | 1   | NA       | *CORNER SIDE PANEL LH     | 0.00  | 0.00  | cur *194.00 F   |
| 25  | 1   | NA       | *WIPER REGULATOR ASSY     | 0.00  | 0.00  | ? *650.00 F     |
| 26  | 1   | NA       | *HEADLAMP RH              | 0.00  | 0.00  | cur *286.00 F   |
| 27  | 1   | NA       | *HEADLAMP LH              | 0.00  | 0.00  | cur *286.00 F   |
| 28  | 1   | NA       | *SIGNAL LAMP RH           | 0.00  | 0.00  | cur *88.00 F    |
| 29  | 1   | NA       | *SIGNAL LAMP LH           | 0.00  | 0.00  | cur *88.00 F    |
| 30  | 1   | NA       | *AIRCON PIPE IN           | 0.00  | 0.00  | ? *226.00 F     |
| 31  | 1   | NA       | *AIRCON OUT PIPE          | 0.00  | 0.00  | ? *172.00 F     |
| 32  | 1   | NA       | *AIRCON SUCTION PIPE      | 0.00  | 0.00  | ? *464.00 F     |
| 33  | 1   | NA       | *CABIN TENSION BRACKET RH | 0.00  | 0.00  | bt *320.00 F    |
| 34  | 1   | NA       | *CABIN TENSION BRACKET LH | 0.00  | 0.00  | bt *320.00 F    |
| 35  | 1   | NA       | *CABIN TENSION BAR        | 0.00  | 0.00  | bt *220.00 F    |
| 36  | 1   | NA       | *BRAKE PUMP ASSY          | 0.00  | 0.00  | ? *1,100.00 F   |
| 37  | 1   | NA       | *STEP GARNISH RH          | 0.00  | 0.00  | X *150.00 F     |
| 38  | 1   | NA       | *STEP GARNISH LH          | 0.00  | 0.00  | cur *150.00 F   |
| 39  | 1   | NA       | *REINFORCEMENT            | 0.00  | 0.00  | bt *1,034.00 F  |
| 40  | 1   | NA       | *BUMPER                   | 0.00  | 0.00  | bt *462.00 F    |
| 41  | 1   | NA       | *BUMPER BRACKET RH        | 0.00  | 0.00  | ? *112.00 F     |
| 42  | 1   | NA       | *BUMPER BRACKET LH        | 0.00  | 0.00  | bt *112.00 F    |
| 43  | 1   | NA       | *RADIATOR ASSY            | 0.00  | 0.00  | ? *750.00 F     |
| 44  | 1   | NA       | *CONDENSER ASSY           | 0.00  | 0.00  | ? *650.00 F     |
| 45  | 1   | NA       | *FAN COWLING ASSY         | 0.00  | 0.00  | ? *138.00 F     |
| 46  | 1   | NA       | *FANBLADE                 | 0.00  | 0.00  | ? *138.00 F     |
| 47  | 1   | NA       | *FAN MOTOR                | 0.00  | 0.00  | ? *85.00 F      |

|    |   |    |                                   |      |      |     |             |
|----|---|----|-----------------------------------|------|------|-----|-------------|
| 48 | 1 | NA | *DOOR RH GLASS                    | 0.00 | 0.00 | cur | *55.00 F    |
| 49 | 1 | NA | *DOOR RH GLASS REGULATOR          | 0.00 | 0.00 | ?   | *120.00 F   |
| 50 | 1 | NA | *DOOR RH LOCK ASSY                | 0.00 | 0.00 | ?   | *150.00 F   |
| 51 | 1 | NA | *DOOR LH GLASS                    | 0.00 | 0.00 | cur | *55.00 F    |
| 52 | 1 | NA | *DOOR LH GLASS REGULATOR          | 0.00 | 0.00 | bt  | *120.00 F   |
| 53 | 1 | NA | *DOOR LH LOCK ASSY                | 0.00 | 0.00 | bt  | *150.00 F   |
| 54 | 1 | NA | *FOGLAMP RH                       | 0.00 | 0.00 | X   | *75.00 F    |
| 55 | 1 | NA | *FOGLAMP LH                       | 0.00 | 0.00 | cur | *75.00 F    |
| 56 | 1 | NA | *CABIN LOCK REGULATOR ASSY        | 0.00 | 0.00 | ?   | *950.00 F   |
| 57 | 1 | NA | *CABIN REAR LOCK BRACKET MOUNT RH | 0.00 | 0.00 | ?   | *220.00 F   |
| 58 | 1 | NA | *CABIN LOCK MOUNTING LH           | 0.00 | 0.00 | ?   | *220.00 F   |
| 59 | 1 | NA | *ENGINE MOUNTING SET              | 0.00 | 0.00 | ?   | *350.00 F   |
| 60 | 1 | NA | *CROSSMEMBER                      | 0.00 | 0.00 | ?   | *1,034.00 F |
| 61 | 1 | NA | *PARKING MIRROR STAND RH          | 0.00 | 0.00 | bt  | *120.00 F   |
| 62 | 1 | NA | *PARKING MIRROR STAND LH          | 0.00 | 0.00 | bt  | *120.00 F   |
| 63 | 1 | NA | *BEZEL COVER RH                   | 0.00 | 0.00 | cur | *15.00 F    |
| 64 | 1 | NA | *BEZEL COVER LH                   | 0.00 | 0.00 | cur | *15.00 F    |
| 65 | 1 | NA | *SIDE MIRROR ROUND COVER RH       | 0.00 | 0.00 | X   | *35.00 F    |
| 66 | 1 | NA | *SIDE MIRROR ROUND COVER LH       | 0.00 | 0.00 | ?   | *35.00 F    |
| 67 | 1 | NA | *DOOR TRIM BOARD RH               | 0.00 | 0.00 | ?   | *550.00 F   |
| 68 | 1 | NA | *DOOR TRIM BOARD LH               | 0.00 | 0.00 | de  | *550.00 F   |
| 69 | 1 | NA | *DOOR SIGNAL LAMP RH              | 0.00 | 0.00 | X   | *55.00 F    |
| 70 | 1 | NA | *DOOR SIGNAL LAMP LH              | 0.00 | 0.00 | cur | *55.00 F    |
| 71 | 1 | NA | *AIR FILTER BOX ASSY              | 0.00 | 0.00 | cur | *230.00 F   |
| 72 | 1 | NA | *AIRCON FILTER ASSY               | 0.00 | 0.00 | ?   | *450.00 F   |
| 73 | 1 | NA | *STEERING BOX                     | 0.00 | 0.00 | ?   | *1,100.00 F |
| 74 | 1 | NA | *STEERING CUPING                  | 0.00 | 0.00 | ?   | *440.00 F   |
| 75 | 1 | NA | *STEERING RACK                    | 0.00 | 0.00 | ?   | *1,750.00 F |
| 76 | 1 | NA | *LOWER ARM RH                     | 0.00 | 0.00 | X   | *330.00 F   |
| 77 | 1 | NA | *LOWER ARM LH                     | 0.00 | 0.00 | X   | *330.00 F   |
| 78 | 1 | NA | *SHOCK ABSORBER RH                | 0.00 | 0.00 | X   | *180.00 F   |
| 79 | 1 | NA | *SHOCK ABSORBER LH                | 0.00 | 0.00 | X   | *180.00 F   |
| 80 | 1 | NA | *BRAKE PIPE                       | 0.00 | 0.00 | ?   | *110.00 F   |
| 81 | 1 | NA | *EARTH HARNESS                    | 0.00 | 0.00 | ?   | *800.00 F   |
| 82 | 1 | NA | *ABS PUMP ASSY                    | 0.00 | 0.00 | ?   | *750.00 F   |
| 83 | 1 | NA | *MAIN KEY LOCK ASSY               | 0.00 | 0.00 | X   | *1,550.00 F |
| 84 | 1 | NA | *TURBO COOLER ASSY                | 0.00 | 0.00 | ?   | *750.00 F   |
| 85 | 1 | NA | *ENGINE ECU ASSY                  | 0.00 | 0.00 | ?   | *1,150.00 F |
| 86 | 1 | NA | *WIPER ARM RH                     | 0.00 | 0.00 | ?   | *70.00 F    |
| 87 | 1 | NA | *WIPER ARM LH                     | 0.00 | 0.00 | ?   | *70.00 F    |
| 88 | 1 | NA | *WIPER BLADE RH                   | 0.00 | 0.00 | cur | *25.00 F    |
| 89 | 1 | NA | *WIPER BLADE LH                   | 0.00 | 0.00 | cur | *25.00 F    |

F=Franchise part.

|                                     |                  |
|-------------------------------------|------------------|
| Sub Total (\$\$)                    | 36,047.00        |
| + Margin on L,N Items 10.00% (\$\$) | 3,604.70         |
| <b>Total Parts (\$\$)</b>           | <b>39,651.70</b> |

Cheng Auto Bodyworks/YP1225G/18/04/2023 09:08. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

| No                         | Qty | Particulars          | Amount   |
|----------------------------|-----|----------------------|----------|
| <u>Miscellaneous Items</u> |     |                      |          |
| 1                          | 1   | AC GAS               | 150.00   |
| 2                          | 1   | BRAKE FLUID          | 100.00   |
| 3                          | 1   | COOLANT              | 60.00    |
| 4                          | 1   | DOOR COMPANY STICKER | 300.00   |
| 5                          | 1   | ERP STICKER          | 25.00    |
| 6                          | 1   | GRILLE CLIPS         | 30.00    |
| 7                          | 1   | NO PLATE             | 35.00    |
| 8                          | 1   | SEALANT A PILLAR     | 100.00   |
| 9                          | 1   | SEALANT CENTRE PANEL | 50.00    |
| 10                         | 1   | SEALANT FLOOR PANEL  | 100.00   |
| 11                         | 1   | SEALANT GLASS        | 60.00    |
| Sub Total (S\$)            |     |                      | 1,010.00 |



## Estimates on Labour

| No                            | Particulars                                                         | Lab.Type | Amount          |
|-------------------------------|---------------------------------------------------------------------|----------|-----------------|
| <b>Labour Items</b>           |                                                                     |          |                 |
| 1                             | LABOUR                                                              | New 1800 | 2,400.00        |
| 2                             | SPRAYPAINTING                                                       | New 1400 | 1,500.00        |
| 3                             | REMOVE AND REINSTALL LINING AND/OR UPHOLSTERY TO FACILITATE REPAIRS | New 150  | 300.00          |
| 4                             | REMOVE AND REPLACE REAR WINDSCREEN                                  | New ✓    | 120.00          |
| 5                             | REMOVE AND REPLACE WINDOW GLASS                                     | New 160  | 200.00          |
| 6                             | REMOVE AND REFIT REAR GLASS CABIN                                   | New ✓    | 60.00           |
| 7                             | REMOVE AND REPLACE AC COMPARTMENT                                   | New 200  | 300.00          |
| 8                             | ALIGNMENT                                                           | New ?    | 80.00           |
| <b>Gross Labour Cost (\$)</b> |                                                                     |          | <b>4,960.00</b> |

Cheng Auto Bodyworks/YP1225G/18/04/2023 09:08. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >