

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 20 Apr 2023

**Preliminary Advice**

|                    |                                                                                            |                         |                |
|--------------------|--------------------------------------------------------------------------------------------|-------------------------|----------------|
| Vehicle No         | : YP1225G                                                                                  | Accident Date           | : 12/04/2023   |
| Make               | : ISUZU NHR85AUE4A                                                                         | Policy No.              | : SP2003732344 |
| Assignment Date    | : 18/04/2023                                                                               | Excess                  | : S\$700.00    |
| Date of Inspection | : 19/04/2023                                                                               | Est. Duration of Repair | : 20           |
| Inspection At      | : CHENG AUTO BODYWORKS (HQ)<br>5 SOON LEE STREET #01-60, PIONEER POINT<br>SINGAPORE 627607 |                         |                |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 45,621.70 |
| Revised Amount              | :S\$ | 16,798.70 |
| Check Items (Estimated)     | :S\$ | 21,879.50 |
| Total                       | :S\$ | 38,678.20 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 36,000.00 |
| COE / PARF Rebate  | :S\$ | 11,492.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 24,508.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ABLE TO REPAIR THE VEHICLE AT REPAIR COST \$19,800.00 ON LUMP SUM BASIS.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.