

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 Email:atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Not Noted
1/1 Rep &
Resurvey After Painting
9 days

Date of Estimate: 17.06.2023
Vehicle No: SGL9991J
Owner: DHURKENDRAN S/O DEVARAJA
Date of Accident: 16.04.2023
Make & Model: KADJAR 1.5 DCI EDC 6AT S&S EU6
Chassis No : VF1RFE00756140861

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE FOR ACCIDENT VEHICLE NO SGL9991J

PARTS

- 1 1 Headlamp RH
- 2 1 Front bumper
- 3 1 Front fender arch garnish RH
- 4 10 Front fender arch garnish clips RH
- 5 1 Front fender RH (repair)
- 6 1 Front door protector garnish LH
- 7 1 Front door protector chrome LH
- 8 1 Front door LH (repair)
- 9 1 Rear door LH
- 10 1 Rear door lock
- 11 1 Rear door protector garnish LH
- 12 1 Rear door protector chrome LH
- 13 12 Rear door protector garnish clips
- 14 1 Rear door window actuator LH
- 15 1 Rear door inner trim LH
- 16 1 Rear door weather strip
- 17 1 Rear fender LH
- 18 1 Rear fender arch garnish
- 19 10 Rear fender arch garnish clips
- 20 1 Rocker panel
- 21 1 Floor panel end top steel plate
- 22 1 Rear wheel bearing hub LH
- 23 1 Rear drive axle

Acknowledged by Repairer
Signature:
Date:

Cur \$3,156.00 ✓
Cur \$2,865.00 ✓
M/I \$840.00 ✓
M \$100.00 ✓
\$0.00
P \$950.00 X
L \$680.00 X
\$0.00
R \$5,700.00 ✓
\$560.00 ✓
M/I \$950.00 ✓
M/I \$680.00 ✓
@ \$10.00 M \$120.00 ✓
\$780.00 ✓
\$755.00 ✓
\$475.00 ✓
R \$3,579.00 ✓
M/I \$840.00 ✓
@ \$10.00 M \$100.00 ✓
K \$2,156.00 ✓
M/I \$456.00 X
\$458.00 ✓
\$7,852.00 ?

SUB TOTAL
LESS 10%
DISCOUNTED SUB TOTAL

\$34,052.00
\$3,405.20
\$30,646.80

S. NETT ITEM

- 1 1 Sport rim X3 P-?
- 2 1 Tyre bridgestone 235/55R18

@ \$900

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

M \$2700 ✓
\$900.00 ✓
M \$420.00 50%
\$1,320.00
\$0.00
\$1,320.00

LABOUR

- 1 Panel beating for replace and repair affected parts
- 2 Spray painting on accident areas
- 3 Wiring charges
- 4 Apply undercoating to above affected areas
- 5 Remove/refix rear quarter windscreen
- 6 Remove/refix rear door LH mechanism

\$1,800.00 1100 ✓
\$1,800.00 900 ✓
\$100.00 20 ✓
\$150.00 60 ✓
\$250.00 60 ✓
\$300.00 60 ✓

SUB TOTAL (LABOUR)
Page 1 of 2

\$4,400.00