

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004002/UVP3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00030772301
Claimant Vehicle No :	SMH3929E	Insured Vehicle No :	GBL2234S
Date of Loss:	17/04/2023	Nature of Claim:	TP
		Claim No:	SNM23D202787/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH3929E	Engine No:	2ZR0C72633
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU00J035629
Reg. Date:	22/01/2019 (Man. Year: 2018)	Odometer:	105309 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Tourador 7 mm	Rear Left Side:	Tourador 7 mm
Front Right Side:	Tourador 7 mm	Rear Right Side:	Tourador 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,039.75	653.32	3,386.43	83.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	420.00	2,630.00	86.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,089.75	1,073.32	6,016.43	84.86
Approved Total (Overridden) (S\$)		850.00		
Nett Amount (S\$)	7,089.75	850.00	6,239.75	88.01

INSPECTION

Date of Assignment:	24/04/2023		
Date Inspected:	19/04/2023	Inspected At:	SPEEDWERKZ PTE LTD (Autobay) (HQ) 1 KAKI BUKIT AVENUE 6 #01-73 Singapore 417883
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2023)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH3929E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	985.90 FL	*- FL
2	1		*REAR BOOT RUBBER	Not Necessary	212.20 FL	*- FL
3	1		*REAR BOOT LOCK	Not Necessary	152.20 FL	*- FL
4	1		*REAR BOOT LOCK CATCH	Not Necessary	82.50 FL	*- FL
5	2		*REAR BOOT HINGE	Not Necessary	170.00 FL	*- FL
6	1		*REAR BOOT CENTRE GARNISH	Not Necessary	185.20 FL	*- FL
7	1		*REAR TAIL LAMP	Not Necessary	485.50 FL	*- FL
8	1		*REAR TAIL LAMP PANEL (RH)	Not Necessary	185.00 FL	*- FL
9	1		*REAR TAIL LAMP GASKET RH	Not Necessary	35.20 FL	*- FL
10	1		*REAR BUMPER	Deep Cut	785.60 FL	*785.60 FL
11	1		*REAR BUMPER LOWER	Not Necessary	475.00 FL	*- FL
12	1		*REAR BUMPER REFLECTOR	Not Necessary	76.30 FL	*- FL
13	1		*REAR REINFORCEMENT BAR	No such part	775.00 FL	*- FL
14	1		*REAR BUMPER SIDE RETAINER	O/S Cracked	91.00 FL	*45.50 FL
15	2		*REAR BUMPER BRACKET	Not Necessary	96.40 FL	*- FL
16	4		*REAR TAIL LAMP CLIPS	Not Necessary	20.00 FS	*- FS
17	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
18	6		*REAR BUMPER LOWER CLIPS	Necessary	30.00 FS	*30.00 FS
19	1		*SET REAR REVERSING SENSOR	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,238.00	861.10
- List Item Discount on L Items 25.00/25.00% (S\$)	1,198.25	207.78
Total Parts (S\$)	4,039.75	653.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	150.00	20.00
2	TUFF KOTE	New	200.00	0.00
3	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,500.00	200.00
4	TO SPRAY PAINTING AND ETC	New	1,200.00	200.00
Gross Labour Cost (\$\$)			3,050.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >