

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III23002425/WVY3E2-1**Date:** 21/04/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02
Claimant Vehicle No : SLF4610P **Insured Vehicle No :** SLZ5614S
 Date of Loss: 04/03/2023 Nature of Claim: TP Claim No: MFL2023D0002901

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF4610P**
 Make & Model: HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: LEB5911669
 Reg. Date: 26/08/2016 (Man. Year: 2016) Chassis No: RU31211658
 Colour: White Odometer: 348764 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Roadstone 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,016.54	953.20	1,063.34	52.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	820.00	1,000.00	54.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,836.54	1,773.20	2,063.34	53.78
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	3,836.54	1,400.00	2,436.54	63.51

INSPECTION

Date of Assignment: 17/04/2023
 Date Inspected: 07/03/2023 Inspected At: 2 Defu South Street 2 #04-06
 Repairer: Perfect Motor (HQ)
 Estimated Period of Repair: 3.0 days

Adjuster: Mohdakid**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2023)
Parts: 144	HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF4610P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Scratched	891.60 FL	*745.10 FL	
2	1		*REAR BUMPER REFLECTOR LH	Not Necessary	111.30 FL	*- FL	
3	1		*REAR BUMPER SIDE LH	Damaged	281.72 FL	*230.00 FL	
4	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	27.28 FL	*- FL	
5	1		*REAR FENDER LH	Repair	789.60 FL	*- FL	
6	1		*REAR FENDER WHEEL ARCH TRIM LH	Scratched	257.92 FL	*128.90 FL	
7	1		*SET REAR BUMPER CLIP	Necessary	55.00 FS	*30.00 FS	
8	1		*SET REAR BUMPER SIDE CLIP LH	Necessary	28.00 FS	*20.00 FS	
9	1		*SET REAR FENDER WHEEL ARCH TRIM CLIP LH	Necessary	46.00 FS	*20.00 FS	
					Sub Total (\$\$)	2,488.42	1,174.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	471.88	220.80
					Total Parts (\$\$)	2,016.54	953.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR & REPLACE DAMAGED PARTS	New	800.00	400.00
2	SPRAY PAINT ON AFFECTED AREA (PEARL WHITE)	New	800.00	400.00
3	CHECK WIRING SYSTEM	New	40.00	20.00
4	REMOVE & REFIX REAR TRIM BOARD & GARNISH	New	100.00	0.00
5	SPRAY ANTI RUST ON AFFECTED AREA	New	80.00	0.00
			Gross Labour Cost (S\$)	1,820.00
				820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >