



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No. M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance



TP INSURER:
LIN YIHAO, CLEMENT

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	13/04/2023
Vehicle Reg. No.:	SML8469L	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA JAZZ, 1.5 VTIR CVT ABS D/AIRBAG 2WD (A)	Vehicle Reg. Date:	15/04/2016
Vehicle Colour:	White		
Engine No:	L15B31020882	Chassis No:	JHMGK5850GX202241
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	3,923.20
Miscellaneous Items	0.00
Labour	2,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,333.20
+ GST 8.00% (S\$)	506.66
Nett Amount (S\$)	6,839.86

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2023)
 Parts: 144 HONDA JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: **Mova Automotive Pte Ltd/SML8469L/17/04/2023 16:57**
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAIL GATE <i>bt</i>	0.00	0.00	*700.00 F
2	1		*TAILGATE GLASS MOULDING <i>AM</i>	0.00	0.00	*40.00 F
3	1		*TAILGATE GLASS SEALANT <i>AM</i>	0	0.00	*40.00 FS
4	1		*TAILGATE GLASS SEALANT <i>AM</i>	0.00	0.00	*14.00 F
4	1		*TAILGATE EMBLEM - JAZZ <i>AM</i>	0.00	0.00	*95.00 F
5	1		*TAILGATE LAMP LH <i>AM</i>	0.00	0.00	*95.00 F
6	1		*TAILGATE INNER TRIM <i>X</i>	0.00	0.00	*70.00 F
7	1		*TAILGATE LOCK <i>X</i>	0.00	0.00	*55.00 F
8	1		*TAILGATE WEATHERSTRIP <i>AM</i>	0.00	0.00	*440.00 F
9	2		*TAILLAMP ASY LH&RH <i>AM</i>	0.00	0.00	*285.00 F
10	1		*REAR END PANEL <i>bt</i>	0.00	0.00	*45.00 F
11	1		*REAR END PANEL TOP COVER <i>ca</i>	0.00	0.00	*370.00 F
12	2		*REAR FENDER INNER TRIM RH & LH <i>X</i>	0.00	0.00	*550.00 F
13	1		*SPARE WHEEL PANEL <i>requr</i>	0.00	0.00	*110.00 F
14	1		*SPARE WHEEL PANEL SPONGE <i>de</i>	0.00	0.00	*100.00 FS
15	1		*SPARE WHEEL PANEL INSULATOR <i>X</i>	0	0.00	*200.00 F
16	1		*REAR BUMPER <i>de</i>	0.00	0.00	*20.00 F
17	2		*REAR BUMPER RETAINER RH & LH <i>AM</i>	0.00	0.00	*20.00 F
18	10		*REAR BUMPER CLIPS <i>AM</i>	0.00	0.00	*45.00 F
19	1		*REAR KEYLESS SENSOR <i>AM</i>	0	0.00	*250.00 FS
20	1		*REVERSE SENSOR <i>AM</i>	0.00	0.00	*58.00 F
21	1		*REAR BUZZER <i>?</i>	0.00	0.00	

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,602.00
+ Margin on L,N Items 10.00% (S\$)	321.20
Total Parts (S\$)	3,923.20

Mova Automotive Pte Ltd/SML8469L/17/04/2023 16:57. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CUTWELD REAR END PANEL, SPARE WHEEL PANEL. KNOCK AND STRAIGHTEN REAR BODY MEMBERS. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTIONS.	New 800	1,000.00
2	SPRAY PAINT TAILGATE, REAR END PANEL, SPARE WHEEL PANEL, REAR BUMPER, REAR BODY MEMBERS.	New 800	1,000.00
3	REMOVE AND REFIX TAILGATE GLASS AND CHECK WATER LEAKAGE.	New	120.00
4	REMOVE AND REFIX TAILGATE INNER TRIM, MECHANISM AND CHECK LOCKING SYSTEM.	New 40	60.00
5	REMOVE AND REFIX LUGGAGE COMPARTMENT INNER TRIM, COVERING, GARNISH.	New 40	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND CHECK FUNCTION.	New 40	60.00
7	RUST PROOF AFFECTED AREAS.	New 60	90.00
Gross Labour Cost (\$\$)			2,410.00

Mova Automotive Pte Ltd/SML8469L/17/04/2023 18:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel
HP 900100 68

7 days

P/P

16/05/23 @ 1550

Resy before
paint