



Your Ref: ACS/105/009/2023/022

Date: 31st May 2023

Our Ref: CS1/SPF23004006/Rqy3m4

M/s Automotive Engrg. & MGT. Division (TP)

Accident Claims Section
(Spore Police Force)
Police Logistics Base (PLB)
1 Hemmant Road
Singapore 438675
(The Motor Claims Department)

Attn: Hafizul Farhan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMZ 1215A
INSURED VEHICLE: GZ 3222L
ACCIDENT DATE: 19/01/2023**

We thank you for your instruction on 18/04/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMZ 1215A from M/s AIG Asia Pacific Insurance Pte Ltd.
- b) Colour damaged vehicle photographs of SMZ 1215A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMZ 1215A
Make & Model	: Toyota Harrier 2.5 Hybrid (2wd) Premium (A)
Chassis Number	: JTEAD3BH80J000346
Year of Registration	: 2021



2. Our finding is that the repair cost of \$9,324.83 (before GST) quoted by M/s AIG Asia Pacific Insurance Pte Ltd is fair & reasonable.

3. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.

Vehicle Inspected By:

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
*B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.