

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	T52159-48966	*COVER RR BUMPER <i>dis</i>		610.40 FL	*610.40 FL
2	1	T52169-48160	*COVER RR BUMPER <i>cut</i>		506.00 FL	*506.00 FL
3	1	T52171-42080	*REINFORCEMENT RR <i>you svc</i>		713.80 FL	Serviceable
4	1	T52615-48330	*ABSORBER RR BUMPER <i>svc</i>		108.30 FL	Serviceable
5	1	T52155-48060	*SUPPORT RR BUMPER <i>svc</i>		123.40 FL	Serviceable
6	1	T52156-48060	*SUPPORT RR BUMPER <i>svc</i>		123.40 FL	Serviceable
7	2	T89348-48320 A0	*RETAINER ULTRASONIC <i>not ne</i>		80.00 FL	*80.00 FL
8	1	T89348-48330 A0	*RETAINER ULTRASONIC <i>ne</i>		40.00 FL	*40.00 FL
9	1	T89348-48340 A0	*RETAINER ULTRASONIC <i>ne</i>		40.00 FL	*40.00 FL
10	1	T58307-48140	*PANEL SUB-ASSY BODY <i>XR</i>		1,166.30 FL	Repair
11	1	T67005-48A60	*PANEL SUB-ASSY BACK <i>st</i>		2,041.00 FL	*2,041.00 FL
12	1	T68105-48924	*GLASS SUB-ASSY BACK <i>ne</i>		1,335.90 FL	*1,335.90 FL
13	1	T75575-48070	*MOULDING BACK <i>ne</i>		31.20 FL	*31.20 FL
14	2	T21000-20	*SIKA 182010 SIKA TACK GOI (BLA <i>ne</i>		216.00 FL	*216.00 FL
15	1	T21000-22	*SIKA 207. G+P ADHESIVE PRIMER <i>ne</i>		200.00 FL	*200.00 FL
16	1	T75442-48170	*PLATE BACK DOOR <i>ne</i>		63.90 FL	*63.90 FL
17	1	T75445-48140	*PLATE BACK DOOR <i>ne</i>		65.60 FL	*65.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,465.20	5,230.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,866.30	1,307.50
<b>Total Parts (S\$)</b>	<b>5,598.90</b>	<b>3,922.50</b>

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SUNDRIES	New	50.00	30.00
2	MERIMEN'S PROCESSING FEES	New	11.00	11.00
3	SUPPLY SEALANT (NETT)	New	60.00	60.00
4	RESET AND REPROGRAMME ECU.	New	162.00	162.00
5	CHK REAR WIRING SYSTEM AND	New	110.16	110.16
6	SUPPLY REGN PLATE (PO#)	New	68.00	68.00
7	DRILL HOLE TO INSTALL REVERSE SENSO	New	162.00	162.00
8	REMOVE TAIL-GATE COMPONENTS TO	New	324.00	324.00
9	REPLACE REAR W/SCREEN GLASS.	New	405.00	405.00
10	SUPPLY AND INSTALL REAR W/SCREEN	New	350.00	350.00
11	REMOVE BOOT INTERIOR TO $\times \wedge \wedge$ Not Require	New	324.00	0.00
12	LABOUR FOR PLATINUM SHINEPRO & SHIN	New	183.18	183.18
13	REMOVE ALL NECESSARY DAMAGED PARTS	New	3,240.00	1,944.00
14	SPRAY PAINT ON DAMAGED AFFECTED	New	2,655.00	1,593.00
			<b>Gross Labour Cost (S\$)</b>	<b>8,104.34</b>
				<b>5,402.34</b>

AIG Asia Pacific Insurance Pte. Ltd./SMZ1215A/03/03/2023 16:00

< END OF REPORT >