

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

JNIS02F2420857403

India International Insurance Pte. Ltd.

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Attn: motor claims Dept

18/4/2023

Estimate cost of repair vehicle no: GBE1594X

Nett Items

2pcs Tail lamp \$248.60x2 *RH cancelled*
 2pcs Tail lamp Panel \$163.40x2 *RH Bent*
 End panel *Repr*
 Tail gate *Repr*
 Tailgate Sticker NISSAN *new*
 2pcs Tailgate Handle \$65x2 *Repr new*
 2pcs Tail gate side Lock \$232.20x2 *new*
 3pcs Tail gate Hinges \$57.20 *new*
 Spare Tyre Holder Lock *new*
 Spare tyre Holder Plate *Bent*
 4pcs stopper \$30x4 *new*
 Number Plate Lamp *new*
 Number Plate Panel *Bent*
 Emblem CABSTAR *new*
 Front windscreen moulding *new*
 Front wiper panel *Repr*
 Front Panel *Deled*
 Emblem 'CABSTAR' *new*
 Front Grille *new*
 Front grille LOGO *new*
 2pcs front Headlamp \$473.40x2 *Cancelled*
 2pcs front headlamp lower garnish \$75x2 *new*
 Front bumper *Deled*
 Front bumper reinforcement *Bent*
 Front bumper top garnish *new*
 10pcs front bumper clip \$6.50x10 *new*
 Air con cooling coil unit *new*

497.20 *248.60*
 326.80 *163.40*
 680.00 +
 1399.70 +
 106.10 -
 130.00 +
 464.40 +
 171.60 +
 551.80 *356*
 67.90 -
 120.00 +
 48.80 +
 79.20 -
 80.00 -
 321.00 +
 494.60 +
 1412.70 -
 45.40 -
 438.40 -
 55.10 -
 946.80 *748*
 150.00 +
 993.40 -
 634.60 -
 48.00 +
 65.00 +
 891.80 +

Air con cooling coil *new*
 Air con blower unit *new*
 Air con Heater unit *crushed*

450.00 *+*
 508.40 *+*
 1810.60 *1403*

S/nett
 Rear stand bar *Best*
 Yellow Sticker *new*
 13 Pax Sticker *new*
 70 km Sticker *new*
 7 Pax Sticker *new*
 IU bracket *new*
 Gum *new*
 2pcs number plate *Best*

300.00 *200*
 150.00 *80*
 20.00 *15*
 20.00 *15*
 20.00 *+*
 25.00 *+*
 60.00 *+*
 80.00 *+*

Reverse Sensor *Dem d*
 Reverse Sensor Bracket *crushed*

280 *200*
160 *50*

To knocking, cutting, welding, renew floor panel, side gate,
 Tail gate and all the damage parts.
 To spray paint on the damage parts.
 To remove, refit front windscreen
 To remove, refit front dashboard
 To remove, renew air con unit
 To refill air con gas
 Tuff Kote
 To check wiring.

1500.00 *1000*
 1300.00 *800*
 150.00 *+*
 280.00 *200*
 200.00 *X*
 120.00 *60*
 100.00 *50*
 45.00 *✓*

To remove reverse sensor

100
50

18,839.30
 Admin *Lj*
 2/s 19/04/23.

08 Days.

F/S 7-11C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: