



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23004012/Rny3m4 Date: 15/06/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	XD 6481A	Veh. Inspected	YN 7962H	
Policy No.	SD22V05240/VCH/R02	Coverage (\$)	0.00	
Claim No.	BVS23/0097	Excess (\$)	0.00	
Assign From	STEWART LIM	Assign Date	17/04/2023	
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R	c.c	4009	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JHHUCS3HX0K011935	Colour	MULTI	
Odometer	473274 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00R16	CONDOR	7 mm	
L/H Front Tyre	7.00R16	CONDOR	7 mm	
R/H Rear Tyre	7.00R16 (D/D)	CONDOR	7/7 mm	
L/H Rear Tyre	7.00R16 (D/D)	CONDOR	7/7 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	20/01/2023	Inspection Date	26/04/2023	
Survey held at	YEE KEONG MOTOR ENGINEERING NO: 14 PENJURU ROAD . SINGAPORE 609125			
5a. Remarks				
A)REGISTRATION DATE: 31 MAR 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	