

**Section A - Accident Details**

Registration Number	SHB5986S
Case Reference Number	TAX/04/23/2034
Registration Date	1/Dec/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	ONG LAY TIN
Type of Accident	Head to Rear
Accident Date and Time	17/Apr/2023 11:10 AM
Accident Reported Date and Time	17/Apr/2023 2:21 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118188
Special Instruction to ARC, if any	TP/ REAR PORTION
Prepared Date and Time	17/Apr/2023 3:37 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$1,416.00	\$200.00
Total Spare Part Cost	\$3,933.19	\$921.45
Total Other Cost	\$500.00	\$65.00
<b>TOTAL COST</b>	<b>\$6,694.19</b>	<b>\$1,386.45 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	6.0	2.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Kenneth Kong (LKK) / INCOME</b>
ARC / Surveyor Sign Off Date	<b>18/04/2023 5:24 PM</b>	<b>18/04/2023 3:39 PM</b>
Signature		<i>Kenneth</i>
Remarks	PART BY PART REPAIR / BEFORE PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com	

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2305-0067	<b>Invoice Number</b>	
<b>Quotation Date</b>	08.05.2023	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$200.00
<b>Total Labour</b>	<b>\$845.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	\$220.00	\$0.00
TO RESPRAY REAR PANEL	\$220.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY FUEL LID COVER	\$220.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,416.00</b>	<b>\$200.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$15.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$500.00</b>	<b>\$65.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check	X
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	Replace	√
		52462-47130	PAD, RR BUMPER, RH & LH , 3	2.00	\$12.00	25.00	\$18.00	Replace	Replace	√
		52462-47030	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
		52462-47020	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$12.00	25.00	\$27.00	Replace	Replace	√
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace	Replace	√
		52599-68030	STOPPER, RR BUMPER, RH & LH	1.00	\$4.80	25.00	\$3.60	Replace	Replace	√
		52576-47060	RETAINER, RR BUMPER, LH	1.00	\$143.60	25.00	\$107.70	Replace	Replace	√
		52592-47080	SEAL, RR BUMPER , LH	0.00	\$128.00	0.00	\$0.00	Replace	Check	X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/05/2023

User ID : PohSuan

	52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
	52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	Replace
	81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	0.00	\$42.20	0.00	\$0.00	Replace	Not Given
	58399-47030	COVER, REAR FLOOR UNDER, LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given
	66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given
	81561-47471	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$367.30	0.00	\$0.00	Replace	Not Given
	81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$282.70	0.00	\$0.00	Replace	Not Given
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check
	89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given
	61602-47180	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$943.10	0.00	\$0.00	Replace	Not Given
	65638-47060	LINER, REAR FENDER, LH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given
	58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given
		STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given
<b>Total</b>				<b>\$4,923.60</b>		<b>\$921.45</b>		

√  
√  
X  
X  
X  
X  
X  
X  
X  
X  
X  
X  
X  
X

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

921.45  
+ 200.00  
+ 265.00  
-----  
1,386.45