

ASS. REC. BY:

REF:

INC/23004014/Kny3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

SMART

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 992G

Yr Regn:

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.G.

1790

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

451087

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKBB3FU103570889

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Falken

195/65R15

R: Sailun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

3

mm

L/Bal.

5

mm

L/Bal.

3

mm

D.O.A.

15/4/23

D.O.I.

18/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/5/23 @ 1100h Car (Red. \$8901.74, 89%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 19/5/23

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS, SI

F. 100

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 17/04/2023

User ID : munsan

Section A - Accident Details


Registration Number	SHB992G
Case Reference Number	TAX/04/23/2027
Registration Date	19/12/17
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN SOON BENG
Type of Accident	Side Swipe
Accident Date and Time	15/4/23 11:35 AM
Accident Reported Date and Time	17/4/23 9:43 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118175
Special Instruction to ARC, if any	TP/ DROVE IN/ RIGHT REAR PORTION
Prepared Date and Time	17/4/23 10:29 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$1,574.00	\$0.00
Total Spare Part Cost	\$4,140.57	\$0.00
Total Other Cost	\$740.00	\$0.00
TOTAL COST	\$7,299.57	\$0.00
Jump Sum Total	\$7,300.00	\$0.00
Number of Repair Days	6.0	3 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	17/04/2023 10:56 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/04/2023

User ID : munsan

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION RH	\$845.00 <i>3001</i>	
Total Labour	\$845.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00 <i>na X</i>	
O RESPRAY REAR FENDER RH	\$378.00 <i>3001</i>	
O RESPRAY RH REAR DOOR	\$378.00 <i>2001</i>	
O RESPRAY ROCKER PANEL MOULDING	\$220.00 <i>1801</i>	
O RESPRAY RIM	\$220.00 <i>na X</i>	
Total Spray Painting & Panel Beating	\$1,574.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00 <i>na X</i>	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>201</i>	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>na X</i>	
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00 <i>na X</i>	
O REMOVE AND REFIT TYRE	\$120.00 <i>na X</i>	
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 <i>na X</i>	
O REPLACE SUNDRY PARTS	\$100.00 <i>na X</i>	
Total Other Costs	\$740.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace <i>(PA)</i>	<i>X N.C</i>
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace <i>na</i>	<i>X</i>
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace <i>na</i>	<i>X</i>
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace <i>na</i>	<i>X</i>
		5246147010	PAD, RR BUMPER, CTR	1.00	\$2.50	25.00	\$1.88	Replace <i>na</i>	<i>X</i>
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace <i>na</i>	<i>X</i>
		5259147050	SEAL, RR BUMPER, RH	1.00	\$95.50	25.00	\$71.63	Replace <i>na</i>	<i>X</i>
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace <i>na</i>	<i>X</i>
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace <i>na</i>	<i>X</i>
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace <i>na</i>	<i>X</i>
		7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace <i>CPT</i>	<i>✓</i>
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace <i>na</i>	<i>X</i>
		6563747060	LINER, REAR FENDER, RH	1.00	\$151.10	25.00	\$113.32	Replace <i>na</i>	<i>X</i>
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace <i>na</i>	<i>X</i>
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR, REAR AXLE, RH & LH	1.00	\$644.10	10.00	\$579.69	Replace <i>na</i>	<i>X</i>
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace <i>na</i>	<i>X</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6855.64

16014.64

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 17/04/2023

User ID : munsan

total					\$6,842.74		\$5,302.45		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									