



Section A - Accident Details

Registration Number	SHB992G
Case Reference Number	TAX/04/23/2027
Registration Date	19/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN SOON BENG
Type of Accident	Side Swipe
Accident Date and Time	15/Apr/2023 11:35 AM
Accident Reported Date and Time	17/Apr/2023 9:43 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118175
Special Instruction to ARC, if any	TP/ DROVE IN/ RIGHT REAR PORTION
Prepared Date and Time	17/Apr/2023 10:29 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,574.00	\$580.00
Total Spare Part Cost	\$5,302.45	\$486.83
Total Other Cost	\$740.00	(\$266.83)
TOTAL COST	\$8,461.45	\$1,100.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / INCOME
ARC / Surveyor Sign Off Date	18/04/2023 5:17 PM	18/04/2023 3:51 PM
Signature		
Remarks	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2305-0068	Invoice Number	
Quotation Date	08.05.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$180.00
TO RESPRAY RIM	\$220.00	\$0.00
Total Spray Painting & Panel Beating	\$1,574.00	\$580.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$286.83)
Total Other Costs	\$740.00	(\$266.83)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	0.00	\$478.90	0.00	\$0.00	Replace	Not Given
		5246247030	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH , 3	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246147010	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given
		5259147050	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given

X
X
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 14/05/2023

User ID : PohSuan

		5256547900	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
		6700347210	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair	R
		7585047910	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$649.10	25.00	\$486.83	Replace	Replace	√
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	100.00	\$0.00	Replace	Repair	R
		6563747060	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
		4261147450	WHEEL, DISC	0.00	\$2,036.30	0.00	\$0.00	Replace	Not Given	X
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR	0.00	\$644.10	0.00	\$0.00	Replace	Not Given	X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
Total					\$6,842.74		\$486.83			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	486.83	
+	300.00	L/S \$1,100/-
+	600.00	
	1,386.83	
	-20%	
	1,109.46	