

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	25-04-23
CLAIM TYPE:	T/P CLAIM
TO:	AIG <i>Xiao Tony</i>
VEHICLE DETAILS	
VEHICLE NO:	SNE421B
MAKE & MODEL:	HYUNDAI CN7 AVENTE 1.6
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	31 March, 2023
TIME:	2240HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 2,024.00	\$ 2,024.00 ✓
2	BOOTLID LOGO <i>New</i>	1	\$ 88.20	\$ 88.20 ✓
3	BOOTLID AVENTE EMBLEM <i>Full</i>	1	\$ 120.00	\$ 120.00 ✓
4	BOOTLID ELITE EMBLEM	1	\$ 80.00	\$ 80.00 ✓
5	BOOTLID LOCK <i>Dnd</i>	1	\$ 230.00	\$ 230.00 ✓
6	BOOTLID LOCK CATCH <i>New</i>	1	\$ 90.00	\$ 90.00 X
7	BOOTLID WEATHERSTRIP <i>New New</i>	1	\$ 190.00	\$ 190.00 X
8	BOOTLID CENTRE LAMP <i>Crashed</i>	1	\$ 1,255.30	\$ 1,255.30 ✓ 1185
8	BOOTLID SENSOR SWITCH DETECTOR <i>New</i>	1	\$ 120.00	\$ 120.00 X
12	REAR NUMBER PLATE (SET) <i>Best New</i>	1	\$ 160.00	\$ 160.00 X
12	REAR BUMPER <i>Dented</i>	1	\$ 620.00	\$ 620.00 ✓ 520
13	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 62.40	\$ 124.80 X
14	REAR BUMPER LOWER LID <i>Dented</i>	1	\$ 420.00	\$ 420.00 ✓
15	REAR BUMPER SENSOR <i>2 pieces dented</i>	4	\$ 220.00	\$ 880.00 ✓ 440
16	REAR BUMPER INNER BRACKET <i>2 pieces dented</i>	5	\$ 30.00	\$ 150.00 ✓ 30
18	REAR BUMPER REINFORCEMENT <i>Dnd</i>	1	\$ 420.00	\$ 420.00 ✓ 384
19	REAR BUMPER REINFORCEMENT BRACKET <i>New</i>	2	\$ 180.50	\$ 361.00 X
20	REAR END PANEL <i>Dented</i>	1	\$ 580.30	\$ 580.30 ✓
22	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 190.30	\$ 190.30 ✓

TOTAL PRICE \$ 8,103.90
LESS 20% \$ 2,025.98

6307.80
5076.24

SUB TOTAL PRICE \$ 6,077.93

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00
4	REAR BUMPER CLIPS SET <i>New</i>	1	\$ 20.00	\$ 20.00
5	REAR BUMPER TOP PROTECTOR <i>New</i>	1	\$ 120.00	\$ 120.00
6	REAR END PANEL TOP GARNISH CLIPS SET <i>New</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL INSULATION SEALANT <i>New</i>	1	\$ 100.00	\$ 100.00
			TOTAL	\$ 310.00

210

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,400.00	\$ 1,400.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,400.00	\$ 1,400.00
3	TUFF COAT	1	\$ 250.00	\$ 250.00
4	WIRING CHECK	1	\$ 100.00	\$ 100.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 150.00	\$ 150.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 80.00	\$ 80.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 80.00	\$ 80.00
8	TRANSFER TAILGATE MECHANISM	1	\$ 120.00	\$ 120.00

1900

TOTAL \$ 3,580.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	6,387.93
TOTAL LABOUR COST	\$	3,580.00
TOTAL REPAIR COST	\$	9,967.93

APPROVED DETAILS:

SURVEYOR:
CONTACT NO.:
PART BY PART/LUMP SUM
NO. OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian
n/s 25/07/23.
06 days

total: 7156.24
L/S: 5.7K