

✓SAS-KIV → see attached

REPAIR ESTIMATE

INSURANCE: INCOME

SURVEYOR: LKK-

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ Ry 459.40
	Rear Bumper Reinforcement	1		\$ Z 394.80
	Rear Bumper Reinforcement Bracket LH / RH	2	\$ 138.10	\$ Z 276.20
	Rear Bumper Side Brackets LH / RH	2	\$ 55.80	\$ X 111.60
	Rear Bumper Centre Moulding	1		\$ de 451.25
	Rear Bumper Lower Centre Moulding	1		\$ X 155.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ re 22.00
	Rear Bumper Reflector Lamp LH / RH	2	\$ 41.45	\$ X 82.90
	Rear Bumper Tow Cover	1		\$ X 98.80
	Rear Bumper FogLamp	1		\$ X 201.50
	Rear Smart Key Antenna	1		\$ X 40.50
	BootLid Emblem – Hybrid	1		\$ X 24.30
	BootLid Emblem – Ioniq	1		\$ re 31.30
	SUB TOTAL		504.55	\$ 2,349.55
	LESS 20%		403.64	\$ 469.91
	DISCOUNTED TOTAL			\$ 1,879.64
	BootLid ComfortDelGro	1		\$ 30.00
	BootLid 65521111	1		\$ 30.00
	BootLid ZIG	1		\$ 40.00
	Reverse Sensors	1		\$ 180.00
	Rear No.Plade With Trim Cover	1		\$ 55.00
	S/NETT SUB			\$ 335.00
	LESS 10%		301.50	\$ 33.50
	S/NETT TOTAL			\$ 301.50
	Rear Bumper Mat	1		\$ 50.00
	Rear Fender Adv.Sticker RH / LH	2	\$ 100.00	\$ 200.00
	BootLid Adv.Sticker	1		\$ 100.00
	SPARE PARTS TOTAL			\$ 2,531.14
	Labour Charge			
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 600.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,520.00
	ESTIMATE TOTAL			\$ 4,051.14

NETT ~~X~~ nm.

NETT ~~re~~ ✓

NETT ~~ant~~

350

500

30

1885.14

4501500

2days

X

Temple 97495747

wp 18/4/23 @ 4pm

6/5 Resum after repair

Temple Michael

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- To display prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- The final repair quantum will be prepared after the
- Supplementary items must be resurveyed and
- Subject to final approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Acknowledged by Repairer

Signature: _____

Date: