

(08/11/13) wef
ASS. REC. BY: Marcus

REF: CC4/AIS23004031/Up93

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBG91194
at Workshop m/s: Enufe
of _____
Insured: SKW 3683H
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: FBG91194 Yr Regn: 10/10/13
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Yamaha FZ1657 c.c. 153
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: Bottom flg T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ME145509AC2022313
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or affected
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 100-80-17
R: 130-70-17
BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear 6
R/Bal. 6 mm R/Bal. _____ mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. 12/04/23 D.O.I. 19/4/23
Survey held at _____
Des. of Damages: 0/5 / Frt / Rear / O/S / N/S / UIC / Rooftop or
Body
The UIC / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 815k.
IDAC Accident Rport: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 0406
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>LTA # 11849 covered 31-12-2032</u>
	<u>2071500 nett 83157</u>
<u>2/5/23</u>	<u>1/5 @ 2300 in hand MR Teo</u>

Date/Time, File Pass to? : Preli. Report
1) : Final Report

Days Of Repair: _____

Date/Time, File Return to?
2) _____

Resurvey No. of Trip: _____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS, SI _____
Photos _____
Others _____
TOTAL _____

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Allianz

Name : **Lim Teck Kee (96496682)**

Accident Date : **12-Apr-23**

Vehicle No : **FBG9119Y (COE31122032)**

Vehicle Model : **Yamaha FZ16ST**

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
	<i>not Allowed</i>	
	<i>19/4/23</i>	
	<i>2/5 \$2300</i>	
	<i>4 days</i>	
	<i>take photo</i>	
1	Front fender <i>R</i>	\$ 185.00 <i>X</i>
2	Fork tube assy <i>u7</i>	\$ 980.00 <i>X</i>
1	Fork under bracket <i>u7</i>	\$ 275.00 <i>X</i>
1	Front brake disc <i>u7</i>	\$ 175.00 <i>X</i>
1	Front rim shaft <i>u7</i>	\$ 95.00 <i>X</i>
1	Front rim bearing <i>u7</i>	\$ 88.00 <i>X</i>
1	Front rim <i>u7</i>	\$ 430.00 <i>X</i>
1	Top cowling <i>cu7</i>	\$ <i>220</i> 350.00 <i>—</i>
1	Headlamp <i>scr</i>	\$ <i>350</i> 680.00 <i>—</i>
1	Lamp stay <i>R</i>	\$ 385.00 <i>X</i>
1	Front signals <i>o/s cu7</i>	\$ <i>60</i> 180.00 <i>—</i>
1	Handle-bar <i>scr</i>	\$ <i>150</i> 280.00 <i>—</i>
1	Handle-bar balancer <i>cu7</i>	\$ <i>40</i> 195.00 <i>—</i>
1	Hand grip (1 set) <i>u7</i>	\$ 85.00 <i>X</i>
2	Side mirror - R/L <i>o/s cu7</i>	\$ <i>80</i> 320.00 <i>1pc</i>
1	Brake lever <i>cu7</i>	\$ <i>82</i> 108.00 <i>—</i>
1	Fuel tank side cover - R/H <i>cu7</i>	\$ <i>180</i> 280.00 <i>—</i>
1	Front side cover <i>R/H cu7</i>	\$ <i>160</i> 300.00 <i>—</i>
1	Front side inner cover <i>R/H cu7</i>	\$ <i>168</i> 320.00 <i>—</i>
1	Front side inner cowling (matt) <i>R/H cu7</i>	\$ <i>110</i> 280.00 <i>—</i>
2	Front footrests <i>o/s cu7</i>	\$ <i>60</i> 188.00 <i>1pc</i>
2	Front footrest brackets <i>u7</i>	\$ 360.00 <i>X</i>
1	Brake pedal <i>cu7</i>	\$ <i>105</i> 175.00 <i>—</i>
1	Exhaust assy <i>o/s</i>	\$ <i>580</i> 880.00 <i>—</i>
1	Exhaust end cap <i>cu7</i>	\$ <i>60</i> 145.00 <i>—</i>
1	Exhaust protector <i>cu7</i>	\$ <i>100</i> 185.00 <i>—</i>
2	Rear footrests <i>u7</i>	\$ 195.00 <i>X</i>
1	Rear footrest bracket <i>u7</i>	\$ 285.00 <i>X</i>
		\$ 8,404.00
	Less 10%*	\$ 840.40
		\$ 7,563.60

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Lim Teck Kee (96496682)

Accident Date : 12-Apr-23

Vehicle No : FBG9119Y (COE31122032)

Vehicle Model : Yamaha FZ16ST

Estimated Repair Costs

<u>Special Nett Items</u>			
1	Number plate (1 set)	11	\$ 38.00 X
2	Fork oils	11	\$ 30.00 X
2	Fork oil seals	11	\$ 56.00 X
1	Steering cone (1 set)	11	\$ 95.00 X
1	Rear side box	117	\$ 220.00 150
1	Rear box	117	\$ 580.00 280
1	Rear box bracket	111	\$ 180.00 X
			\$ 1,199.00

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service (LOD) \$70.00		\$ -
2	To check wiring and reset headlamp focusing	11	\$ 80.00 X
3	To repair body frame	11	\$ 380.00 X
4	To provide labour		\$ 480.00 300
			\$ 940.00

Grand Total \$ 9,702.60

Singapore Dollars: Nine Thousand Seven Hundred Two and Cents: Sixty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-2505
102
2254.5
430
300
2984.5
2387