

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunos Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS23004037/TVY3M4**Date:** 21/07/2023**REFERENCE**

Insured/Claimant: KEVYN SIM JUANQ HUEI Policy No: MPC22B00037600  
Date of Loss: 08/04/2023 Nature of Claim: OD Claim No: DMPC2300255H

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJK7438Z**  
Make & Model: MERCEDES-BENZ E200, 1.8 (A) Engine No: 27195631124817  
Reg. Date: 31/10/2008 (Man. Year: 2008) Chassis No: WDB2110412B390150  
Colour: Black Odometer: 252935 km  
Engine Capacity: 1796 cc  
Market Value/New Car Price: S\$62,000.00  
Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16  
Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm  
Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,171.50	891.00	280.50	23.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	530.00	1,100.00	67.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,801.50</b>	<b>1,421.00</b>	<b>1,380.50</b>	<b>49.28</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,100.00</b>		
<b>(\$\$)</b>	2,801.50	1,100.00	1,701.50	60.74
<b>+ GST 8.00/8.00% (\$\$)</b>	224.12	88.00	136.12	60.74
<b>Nett Amount (\$\$)</b>	<b>3,025.62</b>	<b>1,188.00</b>	<b>1,837.62</b>	<b>60.74</b>

**INSPECTION**

Date of Assignment: 19/04/2023 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)  
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
Date Inspected: 19/04/2023 Inspected At: BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457  
Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2023)
Parts:	143	MERCEDES-BENZ E200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK7438Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Deformed	650.00 F	*650.00 F
2	1		*REAR BUMPER RETAINER RH (WCP)	Not Necessary	30.00 F	*- F
3	1		*REAR BUMPER OUTER TRIM RH (WCP)	Missing	80.00 F	*80.00 F
4	10		*REAR BUMPER CLIP (WCP)	Necessary	80.00 F	*80.00 F
5	1		*REAR TAILLAMP RH (WCP)	Not Necessary	225.00 F	*- F
						F=Franchise part.
					Sub Total (\$\$)	1,065.00 810.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	106.50 81.00
					Total Parts (\$\$)	1,171.50 891.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY & SPRAY PAINTING ON AFFECTED ARAES	New	700.00	250.00
2	TO CHECK WIRING	New	30.00	30.00
3	TO DIAGNOSE & RESET FAULT CODE	New	250.00	0.00
4	TO KNOCK REAR FENDER RH & RR DOOR RH, WELD,REMOVE & FIX ON ABOVE PARTS	New	650.00	250.00
<b>Gross Labour Cost (S\$)</b>			<b>1,630.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >