

Tanah Laka sp. BKS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2023)
Parts: 143 MERCEDES-BENZ E200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJK7438Z)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	0.00	0.00	de / *650.00 F
2	1		*REAR BUMPER RETAINER RH	0.00	0.00	xnn *30.00 F
3	1		*REAR BUMPER OUTER TRIM RH	0.00	0.00	mis / *80.00 F
4	10		*REAR BUMPER CLIP	0.00	0.00	nn / *80.00 F
5	1		*REAR TAILLAMP RH	0.00	0.00	x nn *225.00 F

F=Franchise part.

Sub Total (S\$)	\$810.1	1,065.00
+ Margin on L,N Items 10.00% (S\$)	add 10% = \$89.1	106.50
Total Parts (S\$)		1,171.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
<u>Labour Items</u>			
1	TO PUTTY & SPRAY PAINTING ON AFFECTED ARAES	New 250	700.00
2	TO CHECK WIRING	New ✓	30.00
3	TO DIAGNOSE & RESET FAULT CODE	New 150	xnn 250.00
4	TO KNOCK REAR FENDER RH & RR DOOR RH, WELD, REMOVE & FIX ON ABOVE PARTS	New 250	650.00
Gross Labour Cost (\$\$)			1,530.00 1,630.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$1471-

less 20% → \$136.90

\$1100.10

of 7% per month. shawn
1/7/2017

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC22B00037600	Date of Loss:	08/04/2023
Vehicle Reg. No.:	SJK7438Z	Driveable?	
Driver Age/Info:	50 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KEVYN SIM JUANQ HUEI	Contact No:	+6596579901
Driver:	KEVYN SIM JUANQ HUEI		
Make/Model:	MERCEDES-BENZ E200, 1.8 (A)	Vehicle Reg. Date:	31/10/2008
Vehicle Colour:	BLACK		
Engine No:	27195631124817	Chassis No:	WDB2110412B390150
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Remarks:	VEHICLE IS IN WORKSHOP, PLS ARRANGE TO SURVEY		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	1,171.50
Miscellaneous Items	0.00
Labour	1,630.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	2,801.50
+ GST 8.00% (S\$)	224.12
Nett Amount (S\$)	3,025.62

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tanpin 97495749 / 62563561
 Not Authorise Ex: to be advice
 19/4/23 2350
 L/S Resing after repair
 Tanpin C / Khantow
 2-3 days