



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI23004045/Any3e2

Date: 07/07/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 7604K	Veh. Inspected	SKV 4842P
Policy No.	P10690775R00	Coverage (\$)	0.00
Claim No.	C10021728 /JL	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	19/04/2023

2. Vehicle Particulars & Condition

Make & Model	KIA SORENTO	c.c	2359
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAPH813MF5083679	Colour	WHITE
Odometer	123428 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R19	BRIDGESTONE	6 mm
L/H Front Tyre	235/55 R19	BRIDGESTONE	6 mm
R/H Rear Tyre	235/55 R19	BRIDGESTONE	6 mm
L/H Rear Tyre	235/55 R19	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/04/2023	Inspection Date	19/04/2023
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**