

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TP Budget Direct.
 Hui Rong

JOSEPH TAN CHEE MENG
 BLK 415A NORTHSORE DRIVE #05-543
 SINGAPORE 821415

TAX INVOICE

Repair Code : CLM15866
 Date in : 18/04/2023
 Vehicle Num. : SKV4842P
 Model : KIA SORENTO 2.4(A) GDI HID S/R
 Chassis/Eng# : KNAPH813MF5083679/G4KJFA646908

Contact : 96743355

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Del'd</i>	1	506.00	✓ 506.00
FRONT BUMPER FOGLAMP LH <i>cancel</i>	1	305.00	✓ 305.00
FRONT BUMPER FOGLAMP LH GARNISH (BLACK) <i>Del'd</i>	1	88.00	✓ 88.00
FRONT BUMPER FOGLAMP LH OUTER MOULDING (SILVERY) <i>Del'd</i>	1	90.00	✓ 90.00
FRONT BUMPER LOWER GRILLE (BLACK) <i>new cut</i>	1	168.00	✓ 168.00
FRONT BUMPER LOWER LID (BLACK) <i>new cut</i>	1	506.00	✓ 506.00
FRONT BUMPER LOWER SPOILER (SILVERY) <i>new part</i>	1	175.00	* 175.00
FRONT BUMPER NOZZLE JACK LH <i>cancel</i>	1	196.00	✓ 196.00
FRONT BUMPER NOZZLE JACK LH BRACKET <i>cancel</i>	1	48.00	✓ 48.00
FRONT BUMPER NOZZLE JACK LH COVER <i>missing</i>	1	25.00	✓ 25.00
FRONT BUMPER PARKING SENSOR <i>1 piece changed</i>	2	176.00	176 352.00
FRONT BUMPER PARKING SENSOR HOLDER <i>new</i>	4	20.00	✓ 80.00
FRONT BUMPER PARKING SENSOR O-RING <i>new</i>	2	18.00	✓ 36.00
FRONT BUMPER REINFORCEMENT <i>new</i>	1	493.00	✓ 493.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	28.00	✓ 56.00
FRONT BUMPER SPONGE <i>cancel</i>	1	105.00	✓ 105.00
FRONT LH HEADLAMP <i>cancel</i>	1	2369.00	✓ 2,369.00
FRONT SUPPORT PANEL <i>new</i>	1	662.00	✓ 662.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JOSEPH TAN CHEE MENG
 BLK 415A NORTHSHORE DRIVE #05-543
 SINGAPORE 821415

Contact : 96743355

TAX INVOICE

Repair Code : CLM15866

Date in : 18/04/2023

Vehicle Num. : SKV4842P

Model : KIA SORENTO 2.4(A) GDI HID S/R

Chassis/Eng# : KNAPH813MF5083679/G4KJFA646908

	Subtotal before discount	4662		6,260.00
Percentage discount	10%			626.00
	Sub-total 1	4185.80		5,634.00
FRONT BUMPER CLIPS - SET	1	80.00	30	80.00
FRONT BUMPER NUMBER PLATE	1	25.00	X	25.00
FRONT BUMPER NUMBER PLATE HOLDER	1	50.00	+	50.00
RADIATOR COOLANT	1	80.00	+	80.00
	Subtotal before discount			235.00
Percentage discount	0%			0.00
	Sub-total 2			235.00
	Parts-total			5,869.00

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)			X	120.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)			✓	80.00
To reset system after repair works			+	400.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		910	4W	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.			4W	1,000.00
To apply anti-rust chemical on repaired and replaced panel.			30	120.00
	Labour Total			2,720.00
	Parts & Labour Total			8,589.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey (before/after spray painting)
- To display (used parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

page 2

Acknowledged by Repairer
 Signature:
 Date:

Admin L
 1/5 19/04/23.
 04 Days.
 total: 5135.80
 1/5: 4.11C ✓