

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : SINGAPORE POLICE FORCE
SPF ACCIDENTS CLAIMS SECTION
POLICE LOGISTICS BASE
1 HEMMANT RD, SINGAPORE 438675
TEL: 68428401
ATTN: Motor Claim Department

Estimate No: EST2300157
Date: 18 Apr 2023
Veh Reg No: SCG8008D
Make/Model: TOYOTA NOAH
HYBRID 7-SEATER 1.8
X CVT
Chasis No: ZWR800431289
Reg. Date: 24/07/2020
Your Ref No: QX482P

Claim Type: Third Party
Accident Date: 18/04/2023
TP Veh Reg No: QX482P

Estimate Repair Cost to Vehicle No :SCG8008D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC BOOT LID COVER	1,960.30	
2	1 PC BOOT LID EMBLEM	65.70	
3	1 PC BOOT LID INNER LOCK	446.20	
4	1 PC BOOT LID COVER RUBBER	462.70	
5	1 PC REAR WINDSCREEN GLASS RUBBER	130.40	
6	1 PC REAR BUMPER	669.70	
7	2 PCS REAR BUMPER RETAINER	173.80	
8	1 PC KEYLESS SENSOR	199.80	
9	1 PC REAR PANEL	796.30	
10	1 PC REAR PANEL TRIM	177.90	
		5,082.80	
	Less 25%	1,270.70	3,812.13
Special Net			
11	1 SET REVERSE SENSORS	380.00	
12	1 SET REAR BUMPER CLIPS	60.00	
13	1 SET REAR PANEL TRIM CLIPS	40.00	
14	1 PC REAR WINDSCREEN SEALANT	60.00	
15	1 PC REAR WINDSCREEN RUBBER	60.00	
		600.00	600.00
Labour			
16	1 TO CHECK WIRING	50.00	
17	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
18	1 TO REMOVE AND REFIT INNER TRIM	100.00	
19	1 TO REMOVE AND REFIT SEALANT	80.00	
20	1 (REAR) TO SPRAY PAINTING	900.00	
21	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	900.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : SINGAPORE POLICE FORCE
SPF ACCIDENTS CLAIMS SECTION
POLICE LOGISTICS BASE
1 HEMMANT RD, SINGAPORE 438675
TEL: 68428401
ATTN: Motor Claim Department

Estimate No: EST2300157

Date: 18 Apr 2023

Veh Reg No: SCG8008D

Make/Model: TOYOTA NOAH
HYBRID 7-SEATER 1.8
X CVT

Chasis No: ZWR800431289

Reg. Date: 24/07/2020

Your Ref No: QX482P

Claim Type: Third Party

Accident Date: 18/04/2023

TP Veh Reg No: QX482P

Estimate Repair Cost to Vehicle No :SCG8008D

Quantity	Description	List Price	Amount
		S\$	S\$
		2,150.00	2,150.00
Total			S\$ 6,562.13
Add GST @ 8%			524.97
Total Amount Payable			S\$ 7,087.10

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND EIGHTY SEVEN AND CENTS TEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE