

JAS AUTO SERVICES

UEN: 53255447k

60 JALAN LAM HUAT
#05-06/07 CARROS CENTRE
SINGAPORE 737869

Our Ref : 0
Accident date : 10/4/2023
Your Ref : SLH3227J

Invoice No:

Date : 4/26/2023

Motor Claim Department
Auto & General Insurance(Singapore) Pte Ltd
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
S(239924)

ESTIMATE COST OF REPAIR TO

Vehicle No. : SJQ1775H
Model : Suzuki Swift

1	pc	Rear bumper Deformed	\$	890.00	✓
1	pc	Rear bumper retainer Rh ? X NN	\$	30.00	x
1	pc	Taillamp RH DMG CRA	\$	275.00	✓
1	pc	Rear right rim SCR X NC	\$	495.00	300
1	set	Rear bumper reverse sensors SN DMG (Shurt)	\$	300.00	200

Less 15%

To repair/replace damages
To spray painting
To rust proof

\$	1,990.00	1665
\$	(298.50)	249.75
\$	1,691.50	1415.25
\$	480.00	200 300
\$	680.00	250 400
\$	90.00	x 450
\$	2,941.50	

JAS AUTO SERVICES

2 days.
4 days
Akid 8700 5631
akid@LKKauto.com
Lum Sum

JAS AUTO SERVICES

UEN: 53255447k

60 JALAN LAM HUAT
#05-06/07 CARROS CENTRE
SINGAPORE 737869

Our Ref : 0
Accident date : 10/4/2023
Your Ref : SLH3227J

Invoice No:

Date :

4/26/2023

Motor Claim Department
Auto & General Insurance(Singapore) Pte Ltd
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
S(239924)

SUPPLEMENTARY COST OF REPAIRS TO

Vehicle No. : SJQ1775H
Model : Suzuki Swift

1 pc Rear right fender innershield Cut \$ 107.00 ✓

Less 15%

\$	107.00
\$	(16.05)
\$	90.95 ✓

1415.25 + 90.95
= 1506.2

Labour: 450

1956.2

20% = 391.24

= 1564.96

= \$1560.00

JAS AUTO SERVICES