

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 21 Apr 2023

Preliminary Advice

Vehicle No	: SDG6462B	Accident Date	: 13/04/2023
Make	: INFINITI Q50	Policy No.	: SP2004621676-01
Assignment Date	: 19/04/2023	Excess	: S\$0.00
Date of Inspection	: 20/04/2023	Est. Duration of Repair	: 8
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,125.40
Revised Amount	:S\$	35,947.20
Check Items (Estimated)	:S\$	2,378.20
Total	:S\$	38,325.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	57,421.00
Salvage Value	:S\$	
Margin for Repair	:S\$	62,579.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on part by part basis due to no second hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.