

Q X LNT0

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLK4521L
 Make & Model: Mitsubishi Attrage
 Chassis number: MMBSTA13AHH003738

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid	1	\$ 918.00 918.00
2	Bootlid centre emblem	1	\$ 53.00 53.00
3	Bootlid "Attrage" emblem	1	\$ 24.00 24.00
4	Bootlid "MIVEC" emblem	1	\$ 47.00 47.00
5	Bootlid chrome moulding	1	\$ X 318.00
6	Bootlid chrome moulding clips	1set	\$ X 60.00
7	Bootlid RH hinge	1	\$ X 192.00
8	Bootlid LH hinge	1	\$ X 192.00
9	Bootlid lock	1	\$ X 228.00
10	Bootlid lock catch	1	\$ X 68.00
11	Bootlid weatherstrip	1	\$ X 189.00
12	Rear bumper	1	\$ 704.00 704.00
13	Rear bumper clips	1set	\$ 80.00 80.00
14	Rear bumper RH retainer	1	\$ 34.00 34.00
15	Rear bumper LH retainer	1	\$ X UN 34.00
16	Rear bumper LH reflector	1	\$ 43.00 43.00
17	Rear bumper RH reflector	1	\$ 43.00 43.00
18	LH taillamp assy	1	\$ 435.00 435.00
19	LH taillamp panel	1	\$ X UN 102.00
20	LH taillamp lock clips	1set	\$ X UN 22.00
21	RH taillamp assy	1	\$ 435.00 435.00
22	RH taillamp panel	1	\$ X UN 102.00
23	RH taillamp lock clips	1set	\$ X UN 22.00
24	End panel	1	\$ 455.00 455.00
25	End panel inner garnish	1	\$ 89.00 89.00
26	End panel inner garnish clips	1set	\$ 60.00 60.00
27	End panel air vent	1	\$ X 43.00
28	End panel air vent cover	1	\$ X 54.00
29	End panel RH side cover	1	\$ X 28.00
30	End panel antenna sensor	1	\$ X 105.00
31	End panel buzzer sensor	1	\$ X 98.00
32	LH rear fender inner trim board	1	\$ X 234.00
33	LH rear fender inner trim board clips	1set	\$ X 70.00
34	LH rear fender splash shield	1	\$ X 57.00
35	LH rear fender splash shield clips	1set	\$ X 30.00
36	RH rear fender inner trim board	1	\$ X 234.00
37	RH rear fender inner trim board clips	1set	\$ X 70.00
38	RH rear fender splash shield	1	\$ X 57.00
39	RH rear fender splash shield clips	1set	\$ X 30.00

828.40

335.40

335.40

UN

X UN

40	Spare tyre panel mat	1	\$ X	198.00
41	Spare tyre panel top cover	1	\$ X	339.00
42	Exhaust silencer	1	\$ X	602.00
43	Exhaust silencer gasket	1	\$ X	36.00

3,041.20
2,737.08

Parts less 10% \$ 7,234.00
Total: \$ 723.40
\$ 6,510.60

unx

No.	Special Nett Items	Qty	Amount S\$
1	Bootlid "C&C" emblem	1	\$ unx 80.00
2	End panel joint sealant	1	\$ 4000 80.00
3	Rear bumper reverse sensor	1set	\$ 2000 350.00
4	Rear number plate	1	\$ X 70.00
5	Rear reverse camera	1	\$ X 680.00
6	RH taillamp panel joint sealant	1	\$ X 45.00
7	RH taillamp panel joint sealant	1	\$ X 45.00

Total: \$ 1,350.00

50

unx

290

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 600 1,400.00
2	Spray painting on affected areas and panels	\$ 600 1,200.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 80.00
5	Remove and replace rear bumper reverse sensors to assist repair	\$ 30 80.00
6	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 60 250.00
7	Remove and replace exhaust silencer and hangers to assist repair	\$ X 180.00
8	Remove and replace rear reverse camera to assist repair	\$ 30 100.00
9	Remove and replace bootlid inner components to new bootlid	\$ 60 150.00
		1440

Total: \$ 2,120.00

Agreed Amount: _____ (Part by Part / Lump sum)

faulkin @ khantawon
5 day
- To check consistency of accident
- To check part prices.

2737.08
290
1440
4467.08 #
L/S \$ 3550, 5 days

un.

Working days: _____

Spare Parts:	\$	6,510.60
Special Nett:	\$	1,350.00
Labour:	\$	2,120.00
Total Amount:	\$	<u>9,980.60</u>