



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2303045

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 16/05/2023
Reference CS3/III23004063/Wny3m4
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. FBN 7341Y
Insured Veh. GBJ 8972R
Claim No. MFL2023D0004073
Policy No. D19MFL0005549_03
Accident Date 12/04/2023
Inspection Date 20/04/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 20.04.2023 11.50am	
- Dismantle Inspection 24.04.2023 06.00pm	
- After Repair Inspection 28.04.2023 03.44pm	
Merimen Fee	11.00
Subtotal	131.00
GST (8%)	10.48
Grand Total	141.48

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML