

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH1863
Policy No:	SP2004197935-01	Date of Loss:	15/04/2023
Vehicle Reg. No.:	SLW2200M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HUANG HONGJIUN		
Make/Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Vehicle Reg. Date:	01/02/2018
Vehicle Colour:	RED		
Engine No:	3A92UGR2337	Chassis No:	MMBSTA13AJH001426
Odometer:	82438 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	6,380.00
Miscellaneous Items	240.00
Labour	2,960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,580.00
+ GST 8.00% (S\$)	766.40
Nett Amount (S\$)	10,346.40

This claim is handled by: TAN TING YIGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 19 Apr 2023)**Parts:** N/A MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Wah Hong Motors & Credit Pte Ltd/SLW2200M/19/04/2023 12:04**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Side mirror side garnish RH/LH@2*\$20	0.00	0.00	*40.00 F
2	1		*Wiper side garnish RH/LH@2*\$20	0.00	0.00	*40.00 F
3	1		*Wiper center garnish	0.00	0.00	*120.00 F
4	1		*Bonnet	0.00	0.00	*320.00 F
5	1		*Bonnet hinge RH/LH@2*\$36	0.00	0.00	*72.00 F
6	1		*Bonnet insulator	0.00	0.00	*120.00 F
7	1		*Bonnet lock	0.00	0.00	*50.00 F
8	1		*Front fender RH/LH@2*\$230	0.00	0.00	*460.00 F
9	1		*Front fender emblem "eco" RH/LH@2*\$35	0.00	0.00	*70.00 F
10	1		*Front fender shield RH/LH@2*\$70	0.00	0.00	*140.00 F
11	1		*Headlamp RH/LH@2*\$270	0.00	0.00	*540.00 F
12	1		*Front bumper	0.00	0.00	*300.00 F
13	1		*Front bumper side retainer RH/LH@2*\$15	0.00	0.00	*30.00 F
14	1		*Center grille	0.00	0.00	*280.00 F
15	1		*Center grille logo badge	0.00	0.00	*30.00 F
16	1		*Center lower grille	0.00	0.00	*110.00 F
17	1		*Front bumper lower side garnish RH/LH@2*\$29	0.00	0.00	*58.00 F
18	1		*Radiator top garnish	0.00	0.00	*65.00 F
19	1		*Front reinforcement	0.00	0.00	*130.00 F
20	1		*Condenser	0.00	0.00	*320.00 F
21	1		*Radiator	0.00	0.00	*350.00 F
22	1		*Fan cowling	0.00	0.00	*85.00 F
23	1		*Fan blade	0.00	0.00	*55.00 F
24	1		*Fan motor	0.00	0.00	*240.00 F
25	1		*Support panel	0.00	0.00	*600.00 F
26	1		*Intake manifold	0.00	0.00	*480.00 F
27	1		*Throttle body	0.00	0.00	*600.00 F
28	1		*Wiper tank	0.00	0.00	*60.00 F
29	1		*Spare tank	0.00	0.00	*35.00 F
30	1		*Front door RH/LH (repair refer to labour)	0.00	0.00	*- F
31	1		*A pillar RH/LH (repair refer to labour)	0.00	0.00	*- F

F=Franchise part.

Sub Total (\$\$)	5,800.00
+ Margin on L,N Items 10.00% (\$\$)	580.00
Total Parts (\$\$)	6,380.00

Wah Hong Motors & Credit Pte Ltd/SLW2200M/19/04/2023 12:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Bonnet insulator clip	35.00
2	1	Center grille clip	25.00
3	1	Coolant	50.00
4	1	Front bumper clip	35.00
5	1	Front carplate with holder	35.00
6	1	Front fender shield chip	35.00
7	1	Radiator top garnish clip	25.00
Sub Total (S\$)			240.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,600.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1,200.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00
4	To remove and replace air-con condenser, pipes, vacuum and recharging gas	New	100.00
Gross Labour Cost (S\$)			2,960.00

Wah Hong Motors & Credit Pte Ltd/SLW2200M/19/04/2023 12:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >