



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS3/SPF22007193/Ecy3e2
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROAD SINGAPORE 438675			Date:	31/08/2022
ATTN: HAFIZUL FARHAN			Code:	SPF
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBB 7823L	Veh. Inspected	GBC 3073E	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/045	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	28/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JTFAT35Y70K201787	Colour	SILVER	
Odometer	294671 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	GOODYEAR	4 mm	
L/H Front Tyre	195 R15C	GOODYEAR	4 mm	
R/H Rear Tyre	195 R15C	GOODYEAR	4 mm	
L/H Rear Tyre	195 R15C	GOODYEAR	4 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	25/07/2022	Inspect Date / Time	28/07/2022 (12:27 PM)	
Survey held at	NGEE NGEE MOTOR BLK 1 NO: 22 PANDAN LOOP SINGAPORE 128219			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. GBC 3073E

Qty	Description of Parts	Condition	Recommended (\$)
REPLACEMENT OF PARTS			
1	REAR DOOR	DENTED	1,339.25
1	TAILLAMP LH	CUT	245.00
1	TAILLAMP RH	CUT	245.00
4	REAR DOOR HINGE @\$55.00	BENT	220.00
1	REAR DOOR LOWER PANEL	DENTED	727.43
1	REAR DOOR LOCK LH	BENT	106.00
1	FRONT BUMPER	DENTED	645.30
2	FRONT BUMPER BRACKET @\$191.00	BENT	382.00
1	FRONT GRILLE	BROKEN	517.00
1	FRONT PANEL	DENTED	1,144.00
1	FRONT PANEL CENTRE GARNISH (BLACK)	CUT	279.30
	LESS 25% DISCOUNT		-1,462.57
			4,387.71
SPECIAL NETT ITEMS			
1	70KM/H STICKER (SN)	NECESSARY	20.00
1	13 PERSON STICKER (SN)	NECESSARY	20.00
1	REAR DOOR ALUMINIUM PANEL (SN)	BENT	900.00
1	FRONT LOGO (SN)	NECESSARY	72.00
1	FRONT (DYNA) LOGO (SN)	NECESSARY	61.00
1	ELECTRICAL CHECKING (SN)	NECESSARY	30.00
1	SEALANT (SN)	NECESSARY	40.00
1	UNDERSEAL (SN)	NECESSARY	30.00
1	NUMBER PLATE FRONT (SN)	NECESSARY	35.00
1	NUMBER PLATE REAR & BRACKET (SN)	BENT	150.00
			1,358.00
LABOUR			
	FRONT PORTION LABOUR.		800.00
	REAR PORTION LABOUR.		800.00
	FRONT PORTION SPRAY.		400.00
	REAR PORTION SPRAY.		600.00
			2,600.00
GRAND TOTAL			8,345.71



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	6,650.00
---------------------------------------------------------------------------------	-----------------

Report Ref No. CS3/SPF22007193/Ecy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$6,650-\$7,650

CHEN TSUE YEE
Automotive Assessor

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 3073E

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

