



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III23001932/Wqy3e2-1 Date: 07/06/2023 Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 3920T	Veh. Inspected	SMS 6116G
	Policy No.	D19MFL0005549_03	Coverage (\$)	0.00
	Claim No.	MFL2023D0001833	Excess (\$)	0.00
	Assign From	CARINE KEK	Assign Date	20/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ELEGANCE	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	MR2BE3BE700005953	Colour	GREY
	Odometer	28185 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/02/2023	Inspection Date	27/02/2023
	Survey held at	Blk 7 Sin Ming Industrial Estate Sector C #01-82		
	Repairer	GUAN AUTO SERVICE		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	