



SV AUTOWORKS PTE LTD
8 Kaki Bukit Avenue 4
#02-24 Premier@ Kaki Bukit
Singapore 415875

Estimated Cost of Repair

Attention To:

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details

Case Ref. No.: OD/22023/5984
Date: 13/2/2023
Accident Date: 13/2/2023

Vehicle Details

Make & Model : Renault GRAND SCENIC IV 1.5
DCI AT EU6
Chassis No : VF1RFA00059238203
Registration No : SME2476S

S/N	Description	Qty	Amount (S\$)	
1	FRONT BONNET <i>Brk</i>	1.00	\$ 1,150.00	✓
2	FRONT BONNET RH HINGE <i>Brk</i>	1.00	\$ 110.00	✓
3	FRONT BONNET LH HINGE <i>Brk</i>	1.00	\$ 110.00	✓
4	FRONT BONNET RH RUBBER <i>Scr</i>	1.00	cxl <i>60.00</i>	X
5	FRONT BONNET LH RUBBER <i>Scr</i>	1.00	cxl <i>60.00</i>	X
6	FRONT BONNET INSULATOR <i>crumpled</i>	1.00	\$ 150.00	✓
7	FRONT BONNET LOCK <i>Brk</i>	1.00	\$ 200.00	✓
8	FRONT GRILLE BASE <i>broken</i>	1.00	\$ 400.00	✓
9	FRONT GRILLE OUTER CHROME GARNISH <i>crack</i>	1.00	\$ 290.00	✓
10	FRONT GRILLE MOULDING <i>Brk</i>	1.00	\$ 190.00	✓
11	FRONT GRILLE LOWER CHROME MOULDING <i>crack</i>	1.00	\$ 270.00	✓
12	FRONT GRILLE EMBLEM <i>broken</i>	1.00	\$ 190.00	✓
13	FRONT RH HEADLAMP <i>broken</i>	1.00	\$ 770.00	✓
14	FRONT LH HEADLAMP <i>missing crack</i>	1.00	\$ 770.00	✓
15	FRONT RH HEADLAMP BRACKET <i>Brk</i>	1.00	\$ 50.00	✓
16	FRONT LH HEADLAMP BRACKET <i>HH</i>	1.00	cxl <i>50.00</i>	X
17	FRONT BUMPER <i>turn</i>	1.00	\$ 1,450.00	✓
18	FRONT BUMPER LOWER PAD <i>distorted</i>	1.00	\$ 400.00	✓
19	FRONT BUMPER CENTRE LOWER GRILLE <i>deformed</i>	1.00	\$ 390.00	✓
20	FRONT BUMPER TOWING COVER <i>cut</i>	1.00	\$ 30.00	✓
21	FRONT BUMPER RH FOG LAMP <i>dislodged</i>	1.00	\$ 170.00	✓
22	FRONT BUMPER LH FOG LAMP <i>HH</i>	1.00	cxl <i>170.00</i>	X
23	FRONT BUMPER RH FOG LAMP COVER <i>dislodged</i>	1.00	\$ 170.00	✓
24	FRONT BUMPER LH FOG LAMP COVER <i>HH</i>	1.00	cxl <i>170.00</i>	X
25	FRONT BUMPER RH SIDE RETAINER <i>dislodged</i>	1.00	\$ 110.00	✓
26	FRONT BUMPER LH SIDE RETAINER <i>HH</i>	1.00	\$ 110.00	X
27	FRONT BUMPER RH INNER PAD <i>broken</i>	1.00	cxl <i>90.00</i>	✓
28	FRONT BUMPER LH INNER PAD <i>HH</i>	1.00	\$ 90.00	X

S/N	Description	Qty	Amount (\$\$)	
29	FRONT BUMPER SPONGE <i>broken</i>	1.00	\$ 80.00	✓
30	FRONT BUMPER REINFORCEMENT <i>bt</i>	1.00	\$ 630.00	✓
31	FRONT BUMPER REINFORCEMENT RH BRACKET <i>bt</i>	1.00	\$ 140.00	✓
32	FRONT BUMPER REINFORCEMENT LH BRACKET <i>bt</i>	1.00	\$ 140.00	✓
33	FRONT BUMPER UNDER COVER <i>Crack</i>	1.00	\$ 450.00	✓
34	FRONT BUMPER CLIPS <i>Hec</i>	10.00	\$ 30.00	✓
35	FRONT SUPPORT PANEL <i>broken</i>	1.00	\$ 1,050.00	✓
36	FRONT SUPPORT PANEL TOP COVER <i>broken</i>	1.00	\$ 130.00	✓
37	FRONT SUPPORT PANEL TOP COVER CLIPS <i>Hec</i>	10.00	\$ 30.00	✓
38	AIRCON CONDENSER <i>bt</i>	1.00	\$ 880.00	✓
39	AIRCON CONDENSER DISCHARGE PIPE <i>bt</i>	1.00	\$ 350.00	✓
40	AIRCON CONDENSER RECEIVER PIPE <i>bt</i>	1.00	\$ 280.00	✓
41	AIRCON CONDENSER SUCTION PIPE <i>bt</i>	1.00	\$ 380.00	✓
42	RADIATOR <i>bt</i>	1.00	\$ 690.00	✓
43	RADIATOR TOP HOSE <i>defunct</i>	1.00	\$ 60.00	✓
44	RADIATOR LOWER HOSE <i>Hec</i>	1.00	\$ 60.00	X
45	RADIATOR FAN MOTOR <i>broken</i>	1.00	\$ 870.00	✓
46	TURBO COOLER <i>Defect</i>	1.00	\$ 780.00	✓
47	TURBO COOLER DUCT <i>broken</i>	1.00	\$ 150.00	✓
48	AIR CLEANER BOX <i>broken</i>	1.00	\$ 210.00	✓
49	AIR CLEANER BOX HOSE <i>defunct</i>	1.00	\$ 50.00	✓
50	ALTERNATOR Good <i>Hec</i>	1.00	cxl <i>800-w X</i>	
51	AIRCON COMPRESSOR <i>broken</i>	1.00	\$ 2,000.00	✓
52	FAN BELT <i>ton</i>	1.00	\$ 60.00	✓
53	WIPER TANK <i>Hec</i>	1.00	cxl <i>160-w X</i>	
54	FRONT RH FENDER <i>broken</i>	1.00	\$ 550.00	✓
55	FRONT RH FENDER INNER SHIELD <i>ton</i>	1.00	\$ 310.00	✓
56	FRONT RH FENDER INNER SHIELD CLIPS <i>Hec Hec</i>	10.00	cxl <i>30-w X</i>	
57	FRONT LH FENDER <i>ton</i>	1.00	cxl <i>550-w X</i>	
58	DASHBOARD Good <i>broken</i>	1.00	\$ 3,100.00	✓
59	DASHBOARD COVER broken <i>Hec</i>	1.00	\$ 800.00	X
60	STEERING AIRBAG <i>defunct</i>	1.00	\$ 950.00	✓
61	PASSENGER AIRBAG <i>defunct</i>	1.00	\$ 1,000.00	✓
62	STEERING CLOCK SPRING SENSOR <i>defunct</i>	1.00	\$ 600.00	✓
63	AIRBAG SENSOR <i>defunct</i>	1.00	\$ 220.00	✓
64	AIRBAG ECU <i>defunct</i>	1.00	\$ 1,200.00	✓
65	FRONT RH SEAT BELT <i>defunct</i>	1.00	\$ 630.00	✓
66	FRONT LH SEAT BELT <i>defunct</i>	1.00	\$ 630.00	✓
67	REAR RH SEAT BELT <i>defunct</i>	1.00	\$ 730.00	✓
68	REAR LH SEAT BELT <i>defunct</i>	1.00	\$ 730.00	✓
			\$ 28,520.00	
			\$ 28,520.00	
69	FRONT NO. PLATE <i>cat</i>	1.00	\$ 40.00	✓
			\$ 28,560.00	<i>30700</i>
Discount			20% \$ 22,848.00	<i>24560</i>

S/N	Description	Qty	Amount (S\$)
	Round Up		\$ 22,800.00



SV AUTOWORKS PTE LTD
8 Kaki Bukit Avenue 4
#02-24 Premier@ Kaki Bukit
Singapore 415875

Estimated Cost of Repair (Supplementary)

Attention To:

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details

Case Ref. No.: OD/22023/5984
Date: 13/2/2023
Accident Date: 13/2/2023

Vehicle Details

Make & Model : Renault GRAND SCENIC IV 1.5
DCI AT EU6
Chassis No : VF1RFA00059238203
Registration No : SME2476S

S/N	Description	Qty	Amount (\$)
1	Labour Remove and Repair front panel, front grill, front center panel, front support panel, and other parts	1.00	\$ 4,000.00 1200/-
2	R & R Radiator		\$ 150.00 50/-
3	R & R Condenser		\$ 150.00 120/-
4	R & R Intercooler		\$ 150.00 50/-
5	R & R Dashboard		\$ 300.00 200/-
6	R & R Airbags		\$ 400.00 200/-
7	Airbags resetting and sensor coding		\$ 500.00 350/-
8	Refocus Head Lights		\$ 120.00 30/-
9	Check Wiring		\$ 200.00 30/-
10	Front Windscreen		\$ 250.00 120/-
11	Spray Affected area		\$ 1,800.00 800/-

Ignaz

3030/-

2klc sub

Estimate
Re-mark
on 25/04/2023

8

\$ 8,020.00



SV AUTOWORKS PTE LTD
8 Kaki Bukit Avenue 4
#02-24 Premier@ Kaki Bukit
Singapore 415875

Estimated Cost of Repair (Supplementary)

Attention To:

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details

Case Ref. No.: OD/22023/5984
Date: 13/2/2023
Accident Date: 13/2/2023

Vehicle Details

Make & Model : Renault GRAND SCENIC IV 1.5
DCI AT EU6
Chassis No : VF1RFA00059238203
Registration No : SME2476S

S/N	Description	Qty	Amount (\$\$)	
1	FRONT SUPPORT PANEL AIR DUCT - INNER <i>broken</i>	1.00	\$ 270.00	✓
2	FRONT SUPPORT PANEL AIR DUCT - OUTER <i>broken</i>	1.00	\$ 620.00	✓
3	FRONT SUPPORT PANEL TOP RH BRACKET <i>broken</i>	1.00	\$ 360.00	✓
4	FRONT SUPPORT PANEL TOP LH BRACKET <i>broken</i>	1.00	\$ 350.00	✓
5	FRONT SUPPORT PANEL LOWER RH BRACKET <i>broken</i>	1.00	\$ 130.00	✓
6	FRONT SUPPORT PANEL LOWER LH BRACKET <i>broken</i>	1.00	\$ 130.00	✓
7	RADIATOR AIR DEFLECTOR AIR DUCT <i>broken</i>	1.00	\$ 160.00	✓
8	RH HORN <i>broken</i>	1.00	\$ 260.00	✓
9	ENGINE ECU COVER <i>broken</i>	1.00	\$ 170.00	✓
10	THROTTLE BODY AIR HOSE <i>torn</i>	1.00	\$ 550.00	✓
11	AIR CLEANER BOX AIR HOSE DUCT <i>broken</i>	1.00	\$ 950.00	✓
12	RH FENDER BRACKET <i>broken</i>	1.00	\$ 190.00	✓
13	BONNET LOCK CABLE <i>broken</i>	1.00	\$ 260.00	✓
14	BONNET LOCK RELEASE HANDLE <i>broken</i>	1.00	\$ 90.00	✓
15	ENGINE OIL DIPSTICK <i>broken</i>	1.00	\$ 240.00	✓
16	RH WIPER GRILLE SIDE COVER <i>cut</i>	1.00	\$ 240.00	✓
17	PARKING SENSOR <i>Down</i>	1.00	\$ 750.00	✓
18	PARKING SENSOR WIRE HARNESS <i>torn</i>	1.00	\$ 270.00	✓
19	AIRCON TEMPERATURE SENSOR <i>dislodged</i>	1.00	\$ 170.00	✓
20	BONNET COVER - BLACK <i>broken</i>	1.00	\$ 760.00	✓
21	FRONT RH CHASSIS <i>torn</i>	1.00	\$ 2,500.00	X
22	FRONT LH CHASSIS <i>torn</i>	1.00	\$ 2,500.00	X
			\$ 11,920.00	