



Century Motors



Century Motors (Singapore) Pte Ltd

6 Marsiling Lane

Singapore 739145

E: claims@autoinsure.com.sg

T: (65) 3157 2626

GST No.: 192800002R

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **GBC7984A(CK)**

Your Ref: **SKQ3374G**

Date: **19-Apr-23**

BY EMAIL ONLY
(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

ECICS INSURANCE

10 Eunus Road S,
Singapore Post Centre,
#09-04A,
Singapore 408600

Assessed Vehicle No : **GBC7984A**
Car Make and Model : **TOYOTA HIACE MANUAL**
Date of Accident : **4-Apr-23**
Date of Assessment : **5-Apr-23**

We have carried out a physical assessment of GBC7984A at our workshop Century Motors(Singapore) Pte Ltd sustained damages to the REAR portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount	:	L/S
Adjusted Amount	:	\$ 5,409.24
Est. Repair Days	:	5



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

Century Motors(Singapore) Pte Ltd For any reliance on this report by any third party.

Our Ref: **GBC7984A**

Your Ref: **SKQ3374G**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP	
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1	TAILGATE		\$ 1,950.00	DT 1917
2	1	TAILGATE LOCK		\$ 280.90	TCM ✓
3	1	TAILGATE LOGO		\$ 180.00	NEC 66.7
4	1	TAILGATE EMBLEM(TOYOTA)		\$ 65.80	NEC ✓
5	1	TAILGATE EMBLEM(HIACE)		\$ 65.80	NEC ✓
6	1	REAR BUMPER		\$ 3,472.90	SCR/DT ✓
7	1	REAR BUMPER BRACKET LH		\$ 89.90	X NN
8	1	REAR BUMPER BRACKET RH		\$ 89.90	X NN
SUB TOTAL				\$ 3,148.20	2793.4
LESS 20%				\$ 629.64	558.68
TOTAL AMOUNT				\$ 2,518.56	2234.72

Our Ref: **GBC7984A**

Your Ref: **SKQ3374G**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP	
1	1	REAR BUMPER CLIPS		\$ 60.00	30 NEC
2	1	REAR NUMBER PLATE		\$ 80.00	X NN
3	1	TAILGATE STICKER (70KM/H)		\$ 120.00	20 NEC
SUB TOTAL				\$ 260.00	50
TOTAL PARTS COST				\$ 2,778.56	2284.72

Our Ref: **GBC7984A**

Your Ref: **SKQ3374G**

S/NO	DESCRIPTION	EST. BY WORKSHOP	
	LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1,000.00	400
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 100.00	30
3	TO REMOVE & REFIT REAR WINDSCREEN	\$ 150.00	50
4	TO REMOVE & REFIT TAILGATE MECHANISM	\$ 100.00	x
5	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 600.00	x
6	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 100.00	x
7	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 80.00	x
8	TO VACUUM, WAXING & CLEAN	\$ 50.00	x
9	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 50.00	x
TOTAL BEFORE GST		\$ 5,008.56	4801.12
GST 8%		\$ 400.68	
TOTAL (PARTS & LABOUR):		\$ 5,409.24	2764.72


Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 5,409.24 for lump sum with the third party insurance.

Yours Faithfully,

Ck Loh
Claims Estimator

03 days 

Akid 8700 5631

1500hrs 20104123

akid@lkkauto.com

20% = 552.94

2216.776

~ \$2200.00

20104123

20104123

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: