

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

12-Apr-23

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1662 S

1 pc	Front o/s head lamp	\$	1,531.57 <i>un</i>
1 pc	Bonnet grille	\$	584.31 <i>x un</i>
1 pc	Bonnet grille moulding	\$	40.00 <i>cut</i>
1 pc	Bonnet	\$	1,220.40 <i>Rx</i>
1 pc	Front bumper	\$	811.11 <i>fu</i>
1 pc	Front bumper emblem	\$	27.80 <i>X</i>
1 pc	Front bumper lip	\$	157.15 <i>x</i>
1 pc	Front bumper reinforcement	\$	636.40 <i>x</i>
1 pc	Front bumper sponge	\$	218.03 <i>x</i>
1 pc	Front bumper cap hook	\$	18.25 <i>x</i>
1 pc	Front bumper o/s fog light	\$	840.90 <i>cut</i>
2 pcs	Front bumper n/s & o/s side bracket	\$	65.02 <i>n/s x o/s de</i>
1 pc	Front bumper o/s upper bracket	\$	92.60 <i>X</i>
1 pc	Front bumper o/s support bracket	\$	37.01 <i>X</i>
1 pc	Front o/s rim	\$	246.00 <i>x</i>
1 pc	Front o/s fender	\$	514.02 <i>bu</i>
1 pc	Front o/s fender inner shield	\$	176.72 <i>de</i>
1 pc	Front o/s fender signal lamp	\$	32.10 <i>dis</i>
1 pc	Support panel	\$	1,292.20 <i>un</i>
1 pc	Front o/s wheel housing	\$	869.29 <i>Rx</i>
1 pc	Washer tank	\$	51.40 <i>x</i>
1 pc	Washer tank motor	\$	75.00 <i>x</i>
1 pc	Front o/s door delta moulding	\$	15.30 <i>x</i>
1 pc	Front o/s door	\$	1,723.60 <i>Rx</i>
2 pcs	Front o/s door hinges @ \$39.00	\$	78.00 <i>Rx un</i>
		\$	11,354.18
Less 20%		\$	2,270.84
		\$	9,083.34

5271.13
4216.90

S/NETT

1 set	Front bumper clips	\$	48.00 <i>Bone</i>
1 pc	Front o/s fender sticker	\$	30.00 <i>un</i>
1 set	Front o/s fender inner shield clips	\$	28.00 <i>un</i>
1 set	o/s door stickers	\$	100.00 <i>un</i>

12-Apr-23

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1662 S

Sundry	\$ 50.00 X 24
Towing Fee	\$ 50.00 2
To focus/check front n/s & o/s head lamps	\$ 60.00 30
To check front o/s wheel alignment	\$ 80.00 X 24
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X 24
To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut front o/s wheel housing. Including knock-out, straighten, repair, reshape and adjust of the bonnet, front bumper, front o/s fender, front o/s door, support panel, etc	268
To putty and spray painting on bonnet, front bumper, front o/s fender, front o/s door	600
To apply rustproofing on the repaired and replaced panels.	\$ 2,000.00
	800
	\$ 800.00
	\$ 200.00 30
	\$ 12,709.34

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taughlin 97495749
WP/ 12/4/23 0345pm
L/S Nexing after repair
Taughlin @ 11kanto.com
for 4 days

4216.90
268
1430
5914.90
L/S \$4700
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: