

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	23/AL/OD-215 (04)
Policy No:	SP2004251822-01	Date of Loss:	11/04/2023
Vehicle Reg. No.:	SMX7101R	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YUEN SAI KIT IVAN	Contact No:	+6596224826
Driver:	YUEN SAI KIT IVAN		
Make/Model:	SEAT TOLEDO, 1.4 (A)	Vehicle Reg. Date:	27/01/2021
Vehicle Colour:	BLACK		
Engine No:	CZCA15788	Chassis No:	VSSZZZNHZK1011500
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Remarks:	VEHICLE NOT IN.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	5911.2 11,872.30
Miscellaneous Items	30 65.00
Labour	600 1,730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6541.2 13,667.30
+ GST 8.00% (S\$)	523.3 1,093.38
Nett Amount (S\$)	7064.5 14,760.68

This claim is handled by: **CHIA PEI YING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 20 Apr 2023)**Parts:** N/A SEAT TOLEDO 1.4 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** SME Motor Pte Ltd/SMX7101R/20/04/2023 11:49**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET	0.00	0.00	1,950.00 F DT
2	1		*FRT GRILLE	0.00	0.00	*395.00 F SC
3	1		*FRT GRILLE CHROME	0.00	0.00	*350.00 F SC
4	1		*FRT GRILLE LOGO	0.00	0.00	*85.00 F X
5	4		*FRT GRILLE CLIP	0.00	0.00	*8.00 F NE
6	1		*FRT BUMPER	0.00	0.00	1,850.00 F SC
7	2		*FRT BUMPER RETAINER	0.00	0.00	*160.00 F ?
8	10		*FRT BUMPER CLIP	0.00	0.00	*20.00 F NE
9	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*195.00 F ?
10	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*720.00 F ?
11	2		*HEADLAMP	0.00	0.00	*1,900.00 F BR
12	1		*HEADLAMP SUPPORT PANEL	0.00	0.00	*850.00 F ?
13	2		*HEADLAMP PANEL	0.00	0.00	*270.00 F ?
14	1		*AIRCON CONDENSER	0.00	0.00	*600.00 F ?
15	1		*RADIATOR	0.00	0.00	*550.00 F ?
16	1		*FRT RH FENDER	0.00	0.00	*495.00 F DT
17	1		*FRT BONNET LOCK	0.00	0.00	*395.00 F ?

F=Franchise part.

Sub Total (S\$)	10,793.00 656
+ Margin on L,N Items 10.00% (S\$)	1,079.30 656
Total Parts (S\$)	11,872.30 591

SME Motor Pte Ltd/SMX7101R/20/04/2023 11:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	NUMBER PLATE	3040.00 ¹³⁷¹
2	1	RADIATOR COOLANT	25.00 ^x
Sub Total (S\$)			3065.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 ✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 x
3	LABOUR CHARGE	New	700.00 ⁶⁰⁰
4	SPRAY PAINTING	New	900.00 ⁶⁰⁰
Gross Labour Cost (S\$)			1200 1,730.00

SME Motor Pte Ltd/SMX7101R/20/04/2023 11:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

04 days ^{AK}

AKid 8700 5631

2410412023 1224hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: