

**SME MOTOR PTE LTD**

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883  
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368  
 Email: [service@smemotor.com.sg](mailto:service@smemotor.com.sg) Website: [www.smemotor.com.sg](http://www.smemotor.com.sg)  
 Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	23/AL/OD-215 (04)
Policy No:	SP2004251822-01	Date of Loss:	11/04/2023
Vehicle Reg. No.:	<b>SMX7101R</b>	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YUEN SAI KIT IVAN	Contact No:	+6596224826
Driver:	YUEN SAI KIT IVAN		
Make/Model:	SEAT TOLEDO, 1.4 (A)	Vehicle Reg. Date:	27/01/2021
Vehicle Colour:	BLACK		
Engine No:	CZCA15788	Chassis No:	VSSZZZNHZK1011500
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	7		
Remarks:	VEHICLE NOT IN.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	5911.2
Miscellaneous Items	11,872.30
Labour	30
Paintwork Labour	1,730.00
Towing	0.00
	0.00
<b>Gross Total (S\$)</b>	<b>6541.2</b>
<b>+ GST 8.00% (S\$)</b>	<b>13,667.30</b>
<b>Nett Amount (S\$)</b>	<b>523.3</b>
	1,093.38
	7064.5
	<b>14,760.68</b>

This claim is handled by: **CHIA PEI YING**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

**REPAIR DETAILS****Reference**

Part Source:	(Last Synchronised: 20 Apr 2023)	
Parts:	N/A	SEAT TOLEDO 1.4 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	SME Motor Pte Ltd/SMX7101R/20/04/2023 11:49	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET	0.00	0.00	1600 *1,950.00 F DT
2	1		*FRT GRILLE	0.00	0.00	*395.00 F SC
3	1		*FRT GRILLE CHROME	0.00	0.00	*350.00 F SC
4	1		*FRT GRILLE LOGO	0.00	0.00	*85.00 F X✓ SCR
5	4		*FRT GRILLE CLIP	0.00	0.00	*8.00 F NE
6	1		*FRT BUMPER	0.00	0.00	1600 *1,850.00 F SC
7	2		*FRT BUMPER RETAINER	0.00	0.00	*160.00 F ? X nn
8	10		*FRT BUMPER CLIP	0.00	0.00	*20.00 F NE
9	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*195.00 F ? ✓ CRA
10	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*720.00 F ? X nn
11	2		*HEADLAMP	0.00	0.00	*1,900.00 F BR
12	1		*HEADLAMP SUPPORT PANEL	0.00	0.00	*850.00 F ? ✓ CRA
13	2		*HEADLAMP PANEL	0.00	0.00	*270.00 F ? ✓ DD
14	1		*AIRCON CONDENSER	0.00	0.00	*600.00 F ? ✓ DD
15	1		*RADIATOR	0.00	0.00	*550.00 F ? X nn
16	1		*FRT RH FENDER	0.00	0.00	*495.00 F DT
17	1		*FRT BONNET LOCK	0.00	0.00	*395.00 F ? X nn

F=Franchise part.

Sub Total (S\$)	10,793.00 6561
+ Margin on L,N Items 10.00% (S\$)	1,079.30 6561
Total Parts (S\$)	11,872.30 5911

SME Motor Pte Ltd/SMX7101R/20/04/2023 11:49. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	NUMBER PLATE	3040.00 <del>13.00</del>
2	1	RADIATOR COOLANT	25.00 X
<b>Sub Total (S\$)</b>			<b>3065.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	WIRE CHECKING	New	30.00 ✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 X
3	LABOUR CHARGE	New	700.00 <del>600</del>
4	SPRAY PAINTING	New	900.00 <del>600</del>
<b>Gross Labour Cost (S\$)</b>			<b>1200 1,730.00</b>

SME Motor Pte Ltd/SMX7101R/20/04/2023 11:49. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

04 days *AK*  
AKid 8700 5631  
2410412023 1224hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: