

**Section A - Accident Details**

Registration Number	SHB1051R
Case Reference Number	TAX/04/23/2030
Registration Date	17/Dec/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SHANLAN BIN SHAMSURI
Type of Accident	Side Swipe
Accident Date and Time	15/Apr/2023 9:38 PM
Accident Reported Date and Time	17/Apr/2023 11:06 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118181
Special Instruction to ARC, if any	TP/ RIGHT REAR PORTION/ DROVE IN
Prepared Date and Time	17/Apr/2023 1:10 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,214.00	\$320.00
Total Spray Cost	\$2,152.00	\$500.00
Total Spare Part Cost	\$9,624.16	\$1,813.22
Total Other Cost	\$860.00	\$110.00
<b>TOTAL COST</b>	<b>\$13,850.16</b>	<b>\$2,743.22</b>
<b>Lump Sum Total</b>	<b>\$13,850.00</b>	<b>\$2,750.00 (L/S)</b>
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Kenneth Kong (LKK) / AIG</b>
ARC / Surveyor Sign Off Date	<b>21/04/2023 3:27 PM</b>	<b>21/04/2023 1:57 PM</b>
Signature		
Remarks	INITIAL = 7 DAYS WITH SUPPLEMENTARY = 2 DAYS TOTAL = 9 DAYS	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2305-0070	<b>Invoice Number</b>	
<b>Quotation Date</b>	08.05.2023	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,014.00	\$200.00 ✓
TO REPAIR RH PORTION CENTER	\$200.00	\$120.00 ✓
<b>Total Labour</b>	<b>\$1,214.00</b>	<b>\$320.00</b>

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RIM	\$220.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$180.00 ✓
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$0.00
TO RESPRAY CENTER PILLAR RH	\$200.00	\$120.00 ✓
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$2,152.00</b>	<b>\$500.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$860.00</b>	<b>\$110.00</b>

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Not Given	X R
		52159-47927	COVER, RR BUMPER ASSY	0.00	\$525.40	0.00	\$0.00	Replace	Not Given	X
		52462-47130	PAD, RR BUMPER, RH & LH , 3	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X X SVC
		52462-47030	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X
		52462-47020	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/05/2023

User ID : PohSuan

	52575-47060	RETAINER, RR BUMPER, RH	0.00	\$143.60	0.00	\$0.00	Replace	Not Given	X
	52591-47080	SEAL, RR BUMPER , RH	0.00	\$128.00	0.00	\$0.00	Replace	Not Given	X
	52161-16010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X X SVC
	52453-47900	GUARD, RR BUMPER, LOWER	0.00	\$405.00	0.00	\$0.00	Replace	Not Given	X
	52169-47070	COVER, GUARD RR BUMPER LOWER	0.00	\$23.90	0.00	\$0.00	Replace	Not Given	X
	81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$42.20	0.00	\$0.00	Replace	Not Given	X
	58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
	67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace	√ BT
	68630-47050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X X SVC
	67871-47051	WEATHERSTRIP, REAR DOOR RH	0.00	\$194.60	0.00	\$0.00	Replace	Not Given	X X SVC
	68750-20122	HINGE ASSY, REAR DOOR , UPPER RH	1.00	\$107.00	100.00	\$0.00	Replace	Repair	R
	68770-52031	HINGE ASSY, REAR DOOR , LOWER RH	1.00	\$93.90	100.00	\$0.00	Replace	Repair	R
	85720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Check	X
	69803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$223.50	0.00	\$0.00	Replace	Check	X
	75850-47910	MOULDING ASSY, BODY ROCKER PANEL , RH	0.00	\$649.10	0.00	\$0.00	Replace	Not Given	X X SVC
	67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	0.00	\$1,407.80	0.00	\$0.00	Replace	Not Given	X
		STICKER STRIDES TAXI ( DOOR )	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
	61601-47150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$943.10	0.00	\$0.00	Replace	Not Given	X
	4261147450	WHEEL, DISC	0.00	\$2,036.30	0.00	\$0.00	Replace	Not Given	X
	42450-76020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR	0.00	\$644.10	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>				<b>\$10,799.90</b>		<b>\$1,051.28</b>			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		68750-20122	HINGE ASSY, REAR DOOR , UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	Replace	√ DIS
		68770-52031	HINGE ASSY, REAR DOOR , LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	Replace	√ DIS
		85720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	1.00	\$996.60	10.00	\$896.94	Replace	Replace	√ BT
		69803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1.00	\$223.50	25.00	\$167.63	Replace	Replace	√ JM
<b>Total</b>					<b>1,421.00</b>		<b>1,215.25</b>			

	2,266.53	
	<u>-20%</u>	
	1813.22	L/S \$2,750/-
+	320.00	
+	<u>610.00</u>	
	2,743.22	