

Not Authenital
1/Imp &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5990T

AAD2304-

D2

Vehicle No.:

Chassis No.:

UEN No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 APR 2023

SHD5990T

JTDKB3FU903074966

200303878K

TOYOTA

PRIUS

25/3/2023

SNG2005X/ Allianz-

1/11/2018

PART

LIST

- 1 PANEL SUB-ASSY, FRONT DOOR, RH
- 1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH
- 1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, RH
- 1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH
- 1 HINGE ASSY, FRONT DOOR, LOWER RH
- 1 HINGE ASSY, FRONT DOOR, UPPER RH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH
- 1 TAPE, BLACK OUT, NO.2 FRT RH
- 1 TAPE, BLACK OUT, NO.1 FRT RH
- 1 TAPE, BLACK OUT, NO.3 FRT RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 FRONT FENDER EMBLEM RH
- 1 BRACE SUB-ASSY, FENDER APRON, RH
- 1 LINER, FRONT FENDER, RH
- 1 COVER, FRONT BUMPER
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 UNIT ASSY, HEADLAMP, RH
- 1 LAMP ASSY, FOG, RH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 COVER SUB-ASSY, FRONT PILLAR, UPR RH
- 1 ABSORBER ASSY, SHOCK, FRONT RH
- 1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH
- 1 KNUCKLE, STEERING, RH
- 1 HUB SUB-ASSY, FRONT AXLE, RH
- 1 MOULDING ASSY, BODY ROCKER PANEL, RH
- 1 RIM

\$	R ₂	1,641.36	✓
\$	R ₂	243.81	X
\$	R ₂	493.40	X
\$	R ₂	1,161.83	X
\$	R ₂	404.57	X
\$	R	139.86	X
\$	R	123.06	X
\$	R ₂	300.62	X
\$	R ₂	55.02	✓
\$	R ₂	16.91	✓
\$	R ₂	33.29	✓
\$	R ₂	1,236.69	✓
\$	R ₂	68.88	✓
\$	R	368.24	X
\$	D ₁	260.51	✓
\$	CM	653.31	✓
\$		214.41	?
\$	R ₂	436.38	X
\$	R ₂	276.15	✓
\$	mg cm	3,325.56	✓
\$	R ₂	1,200.78	X
\$	D ₁	100.49	✓
\$	R ₂	100.17	X
\$	D ₁	74.97	✓
\$	mg	126.74	✓
\$	R ₂	554.72	✓
\$	R ₂	959.81	✓
\$	R ₂	836.64	✓
\$	R ₂	841.89	✓
\$	D ₁	624.54	✓
\$	R ₂	1,900.10	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5990T**AAD2304-**

TOTAL	\$	18,774.68
25%	\$	4,693.67
	\$	14,081.01

Special Nett

1	DOOR STICKER TRANSCAB	\$	<i>na</i>	100.00	<i>60/na</i>
1	DOOR TRIM CLIP	\$	<i>na</i>	75.00	<i>X</i>
1	DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	80.00	<i>X</i>
1	FRT DOOR ADVERTISEMENT	\$	<i>na</i>	200.00	<i>100/na</i>
1	FRT BUMPER CLIP	\$	<i>na</i>	65.00	<i>60/na</i>
1	FRT NUMBER PLATE WITH MOULDING	\$	<i>na</i>	180.00	<i>X</i>
1	FENDER LINER CLIP	\$	<i>na</i>	65.00	<i>—</i>
1	ROCKER MOULDING CLIP	\$	<i>na</i>	65.00	<i>—</i>
1	TYRE	\$	<i>na</i>	350.00	<i>80/na</i>
TOTAL	\$	1,180.00			

TOTAL PARTS	\$	15,261.01
--------------------	-----------	------------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>60/na</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>60/na</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>60/na</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>20/na</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2304-**SHD5990T**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	700/
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	880/
To transfer of tire, rim and on wheel balancing.	\$	<i>Repair</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
TOTAL	\$	5,110.00	
Over All Total	\$	20,371.01	

(PART-BY-PART) Repair Days*09 Days**5 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: