

ASS. REC. BY:

REF:

ALS/230041011ky

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 39,780/-

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S14D 59POT Yr Regn: 11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Proace c.c. 1798Colour M.P. White / Red A/C: Insured / Std / NI / NASp. Reading 285472 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J7DKB3FU903074966Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / A/Rim or

Tyre Size: Grandeur 195/65R15R: Wanli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 5 mmL/Bal. 9 mmL/Bal. 5 mmD.O.A. 25/3/23D.O.I. 18/4/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/4 21:00 @ 10,050/- Cash

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Not Authored
11 Sep & 10,050ph

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5990T

AAD2304-

Vehicle No.:

Chassis No.:

UEN No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 APR 2023

SHD5990T

JTDKB3FU903074966

200303878K

TOYOTA

PRIUS

25/3/2023

SNG2005X/ Allianz-

1/11/2018

PART

LIST

- 1 PANEL SUB-ASSY, FRONT DOOR, RH
- 1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH
- 1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, RH
- 1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH
- 1 HINGE ASSY, FRONT DOOR, LOWER RH
- 1 HINGE ASSY, FRONT DOOR, UPPER RH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH
- 1 TAPE, BLACK OUT, NO.2 FRT RH
- 1 TAPE, BLACK OUT, NO.1 FRT RH
- 1 TAPE, BLACK OUT, NO.3 FRT RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 FRONT FENDER EMBLEM RH
- 1 BRACE SUB-ASSY, FENDER APRON, RH
- 1 LINER, FRONT FENDER, RH
- 1 COVER, FRONT BUMPER
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 UNIT ASSY, HEADLAMP, RH
- 1 LAMP ASSY, FOG, RH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 COVER SUB-ASSY, FRONT PILLAR, UPR RH
- 1 ABSORBER ASSY, SHOCK, FRONT RH
- 1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH
- 1 KNUCKLE, STEERING, RH
- 1 HUB SUB-ASSY, FRONT AXLE, RH
- 1 MOULDING ASSY, BODY ROCKER PANEL, RH
- 1 RIM

\$	R ₁	1,641.36	✓
\$	P ₁	243.81	X
\$	P ₁	493.40	X
\$	P ₁	1,161.83	X
\$	S ₁	404.57	X
\$	R	139.86	X
\$	R	123.06	X
\$	P ₁	300.62	X
\$	R ₁	55.02	✓
\$	R ₁	16.91	✓
\$	R ₁	33.29	✓
\$	R ₁	1,236.69	✓
\$	R ₁	68.88	✓
\$	R	368.24	X
\$	D ₁	260.51	✓
\$	C ₁	653.31	✓
\$	P ₁	214.41	X
\$	P ₁	436.38	X
\$	R ₁	276.15	✓
\$	R ₁	3,325.56	✓
\$	S ₁	1,200.78	X
\$	D ₁	100.49	✓
\$	R	100.17	X
\$	D ₁	74.97	✓
\$	M ₁	126.74	✓
\$	R ₁	554.72	✓
\$	R ₁	959.81	✓
\$	R ₁	836.64	✓
\$	R ₁	841.89	✓
\$	D ₁	624.54	✓
\$	R ₁	1,900.10	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5990T**AAD2304-**

TOTAL	\$	18,774.68
25%	\$	4,693.67
	\$	14,081.01

Special Nett

- 1 DOOR STICKER TRANSCAB
- 1 DOOR TRIM CLIP
- 1 DOOR WEATHERSTRIP CLIP
- 1 FRT DOOR ADVERTISEMENT
- 1 FRT BUMPER CLIP
- 1 FRT NUMBER PLATE WITH MOULDING
- 1 FENDER LINER CLIP
- 1 ROCKER MOULDING CLIP
- 1 TYRE

\$	Per	100.00	60sn
\$	na	75.00	X
\$	na	80.00	X
\$	na	200.00	100sn
\$	na	65.00	60sn
\$	na	180.00	X
\$	na	65.00	—
\$	na	65.00	—
\$	na	350.00	80sn
\$	224sn		
TOTAL	\$	1,180.00	

TOTAL PARTS	\$	15,261.01
--------------------	-----------	------------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	601
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	Perman 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd**AAD2304-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5990T

Panel Beating, Knocking And Straightening The Necessary

Portion, Remove And Renewal Of Parts, Adjust And Realign The
Same

\$ 1,600.00

700/

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00

880/

To transfer of tire, rim and on wheel balancing.

\$ 170.00

Rim

X

To Check Electrical Lighting Concerned.

\$ 170.00

20/

TOTAL \$ 5,110.00**Over All Total \$ 20,371.01****(PART-BY-PART) Repair Days**

09 Days

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD5990T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Apr 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B96336
Chassis No.:	JTDKB3FUX03078959
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	11 Jan 2019
First Registration Date:	11 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,838.00
COE Rebate Amount:	\$9,739.00
Total Rebate Amount:	\$20,424.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Apr 2023

OK