



VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-136, Enterprise Hub
Singapore 608586

Repair Estimate

Tel: 6267 9916
Fax: 6267 9313
www.avantage.sg

Date : 17-Apr-2023

Vehicle Num : SDF800D

Make/Model : Volkswagen Golf A7 1.4 TSI AT

Chassis No : WVWZZZAUZFW357452

S/N	PARTS	QTY	PRICE	TOTAL
1	Bonnet	1	\$ 1,440.96	\$ 1,440.96
2	LH Hinge, Bonnet	1	\$ 81.68	\$ 81.68
3	RH Hinge, Bonnet	1	\$ 81.68	\$ 81.68
4	Lock, Bonnet	1	\$ 180.89	\$ 180.89
5	LH Front Fender	1	\$ 477.92	\$ 477.92
6	Radiator Grille	1	\$ 387.21	\$ 387.21
7	Front Bumper	1	\$ 882.10	\$ 882.10
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
	TOTAL PARTS			\$ 3,532.44
	Less 10%			\$ 353.24
	TOTAL AMOUNT			\$ 3,179.20
MISCELLANEOUS ITEM				
1	Sunderies		\$ 40.00	\$ 40.00
2	Tuff Kote		\$ 50.00	\$ 50.00
3	Front Licence Plate with Casing.		\$ 45.00	\$ 45.00
4	Ceramic Coating for Bonnet and LH Front Fender. <i>provide receipt</i>		\$ 300.00	\$ 300.00
LABOUR				
1	Remove and refit Bonnet, Hinges, Lock, Radiator Grille, LH Front Fender, Bumper and other associate components.	320	\$ 800.00	\$ 480
2	Surface preparation, spray paint and polish Bonnet, Hinges, LH Front Fender, Bumper and other affected areas.	250	\$ 800.00	\$ 750
3	Diagnostic check and erase fault codes after the repair.		\$ 80.00	\$ 80.00
<i>Tan Jiah 97495749/62363561</i> <i>wp 19/4/23 @ 7pm</i> <i>plz Resurvey before paint</i> <i>Tan Jiah @ lkkauto.com</i> <i>04 days</i>				
	TOTAL			\$ 5,294.20
	GST 8%			\$ 423.54
	GRAND TOTAL			\$ 5,717.74