


JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 18.04.2023

TO : LONPAC MOTOR CLAIMS DEPTS
VEHICLE NO : SMC2896Z
MODEL : HONDA VEZEL HRV
DATE OF ACCIDENT : 17.04.2023
TIME OF ACCIDENT : 09:05 HOURS

Ezlynn

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 865.50	\$ 865.50
2	REAR BUMPER REFLECTOR <i>RH and L</i>	2	\$ 151.10	\$ 302.20
3	REAR BUMPER SIDE <i>RH torn</i>	2	\$ 230.00	\$ 460.00
4	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 57.00	\$ 114.00
5	TAIL LAMP <i>and L</i>	2	\$ 475.00	\$ 950.00
6	TAILGATE <i>Dented</i>	1	\$ 1,420.00	\$ 1,420.00
7	TAILGATE NUMBER PLATE LAMP <i>new</i>	2	\$ 85.00	\$ 170.00
8	TAILGATE LOGO <i>HRV new</i>	1	\$ 65.00	\$ 65.00
9	TAILGATE EMBLEM 'VEZEL' <i>new</i>	1	\$ 68.00	\$ 68.00
10	TAILGATE EMBLEM 'I-VTEC' <i>new</i>	1	\$ 65.00	\$ 65.00
11	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 220.00	\$ 220.00
12	TAILGATE SIDE LAMP <i>RH and L</i>	2	\$ 240.00	\$ 480.00
13	TAILGATE INNER HOLDER <i>new</i>	1	\$ 52.00	\$ 52.00
14	TAILGATE STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00
15	TAILGATE TOP LOCK <i>Damaged</i>	1	\$ 180.00	\$ 180.00
16	TAILGATE LOWER LOCK <i>new</i>	1	\$ 24.70	\$ 24.70
17	TAILGATE INNER TRIM <i>cracked</i>	1	\$ 398.60	\$ 398.60
18	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 168.40	\$ 168.40
19	TAILGATE WINDSCREEN MOULDING (SET) <i>new</i>	1	\$ 164.00	\$ 164.00
20	TAILGATE LOCK CONNECTOR <i>new and L</i>	1	\$ 379.00	\$ 379.00
21	BUZZER <i>new</i>	1	\$ 109.00	\$ 109.00

592.

151.10

230

57.

1053

240

240

240

240

240

240

240

240

240

240

240

240

240

240

240

240

240

TO : LONPAC MOTOR CLAIMS DEPTS
 VEHICLE NO : SMC2896Z
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 17.04.2023
 TIME OF ACCIDENT : 09:05 HOURS

22	REAR FENDER INNER TRIM <i>RH covered</i>	2	\$ 399.10	\$ 798.20	<i>399.10</i>
23	REAR FENDER COWLING <i>new</i>	2	\$ 150.20	\$ 300.40	<i>+</i>
24	REAR FENDER ARCED GARNISH <i>new</i>	2	\$ 184.70	\$ 369.40	<i>+</i>
25	REAR END PANEL <i>Dented</i>	1	\$ 530.00	\$ 530.00	<i>-</i>
26	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 146.30	\$ 146.30	<i>-</i>
27	REAR FLOOR PANEL <i>Repair</i>	1	\$ 1,130.00	\$ 1,130.00	<i>+</i>
28	REAR FLOOR PANEL BOTTOM GARNISH <i>Dented</i>	1	\$ 269.00	\$ 269.00	<i>-</i>
29	REAR FLOOR TOWING PANEL <i>new</i>	1	\$ 545.00	\$ 545.00	<i>+</i>
30	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 300.40	\$ 300.40	<i>-</i>
31	REAR STORAGE BOX <i>covered</i>	1	\$ 495.00	\$ 495.00	<i>295</i>
32	CENTER EXHAUST GASKET (SET) <i>2 2</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
33	CENTER EXHAUST	1	\$ 1,448.00	\$ 1,448.00	<i>+</i>
34	CENTER EXHAUST INSULATOR	1	\$ 89.00	\$ 89.00	<i>+</i>
35	REAR EXHAUST <i>Repair</i>	1	\$ 980.00	\$ 980.00	<i>7</i>
36	REAR EXHAUST INSULATOR	1	\$ 55.00	\$ 55.00	<i>+</i>
37	REAR EXHAUST MOUNTING	4	\$ 18.00	\$ 72.00	<i>+</i>
38	REAR EXHAUST GASKET (SET)	1	\$ 80.00	\$ 80.00	<i>+</i>
39	REVERSE CAMERA <i>new</i>	1	\$ 1,358.60	\$ 1,358.60	<i>+</i>
40	REVERSE SENSOR (SET) <i>Dented</i>	1	\$ 650.00	\$ 650.00	<i>400 (SN)</i>

6406.90
5125.52
S.N: 400

TOTAL PRICE \$ 16,389.70
 LESS 20% \$ 3,277.94
 SUB TOTAL PRICE \$ 13,111.76

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS					
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$	80.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$	80.00
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$	60.00
4	TAILGATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$	60.00
5	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$	80.00
6	TAILGATE WINDSCREEN SEALANT <i>3 new</i>	1	\$ 80.00	\$	80.00
7	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$	60.00
8	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$	80.00
9	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$	80.00

TO : LONPAC MOTOR CLAIMS DEPTS

VEHICLE NO : SMC2896Z

MODEL : HONDA VEZEL

DATE OF ACCIDENT : 17.04.2023

TIME OF ACCIDENT : 09:05 HOURS

10	REAR FENDER ARCED GARNISH CLIP (SET) <i>Mer</i>	1	\$ 80.00	\$ 80.00	<i>f</i>
11	REAR END PANEL TOP GARNISH CLIP (SET) <i>Mer</i>	1	\$ 60.00	\$ 60.00	<i>20</i>
12	REAR END PANEL INSULATION SEAL <i>Mer</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
13	REAR FLOOR PANEL SEALANT <i>Mer</i>	1	\$ 350.00	\$ 350.00	<i>f</i>
14	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>Mer</i>	1	\$ 80.00	\$ 80.00	<i>30</i>

290
TOTAL \$ 1,380.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	<i>90</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>90</i>
3	TUFF COAT	\$ 250.00	<i>80</i>
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>80</i>
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	<i>50</i>
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>x</i>
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>/</i>
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>80</i>
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	<i>x</i>

TO : LONPAC MOTOR CLAIMS DEPTS
VEHICLE NO : SMC2896Z
MODEL : HONDA VEZEL
DATE OF ACCIDENT : 17.04.2023
TIME OF ACCIDENT : 09:05 HOURS

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 5,300.00 2310

TOTAL PARTS COST : \$ 14,491.76
TOTAL LABOUR COST : \$ 5,300.00
TOTAL REPAIR COST : \$ 19,791.76

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 8125.52

L/S: 6.5K

Adrian L
L/S 19/04/23.
06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: