



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR23004109/Kvy3m4 Date: 24/05/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 1380G	Veh. Inspected	BJT 679
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/04/23/5022	Excess (\$)	0.00
Assign From	ASHLENE LEE	Assign Date	20/04/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (M)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	PN1HS02PX04000300	Colour	SILVER
Odometer	243018 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195R 15X8	MICHELIN	6 mm
L/H Front Tyre	195R 15X8	MICHELIN	6 mm
R/H Rear Tyre	195R 15X8	MICHELIN	6 mm
L/H Rear Tyre	195R 15X8	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/04/2023	Inspection Date	04/05/2023
Survey held at	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	