



JACK CARS

DRIVE WITH ASSURANCE

ESTIMATE

DATE OF ACCIDENT : 19/04/2023
VEHICLE : SNF2033U
MAKE & MODEL : HONDA SHUTTLE
INSURANCE : EQ INSURANCE
SURVEYOR : LKK

PARTS		AMOUNT
1.	REAR BOOT <i>Dented</i>	\$ 1800
2.	REAR BOOT INNER COVER ?	\$ 590 ?
3.	REAR BOOT CHROME GARNISH <i>crushed</i>	\$ 330 ✓
4.	REAR BOOT WEATHERSTRIP <i>the pin</i>	\$ 220 +
5.	TAILLAMP - LEFT INNER <i>cut</i>	\$ 670
6.	TAILLAMP - LEFT INNER LOWER <i>new</i>	\$ 380 +
7.	TAILLAMP - LEFT OUTER <i>cut</i>	\$ 770
8.	TAILLAMP - RIGHT INNER <i>crushed</i>	\$ 670
9.	TAILLAMP - RIGHT INNER LOWER <i>new</i>	\$ 380 +
10.	TAILLAMP - RIGHT OUTER <i>cut</i>	\$ 770 ✓
11.	REAR END PANEL <i>Repair</i>	\$ 790 +
12.	REAR END PANEL TOP COVER ?	\$ 190 ?
13.	REAR BUMPER <i>Repair & Rebrand</i>	\$ 980 ✓



JACK CARS

DRIVE WITH ASSURANCE

14.	REAR WINDSCREEN WEATHERSTRIP <i>New</i>		\$ 340 <i>145</i>
	SPECIAL NETT		
1.	REAR NUMBER PLATE & COVER <i>New</i>		\$ 95 <i>x</i>
2.	CLIPS , RIVETS & SCREWS <i>Me</i>		\$ 100 <i>30</i>
3.	REAR WINDSCREEN <i>New</i>		\$ 2300 <i>x</i>
4.	WINDSCREEN SEALANT <i>Me</i>		\$ 150 <i>60</i>
5.	"HONDA" EMBLEM <i>new</i>		\$ 95 <i>45</i>
	LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 1500 <i>500</i>
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.		\$ 2500 <i>400</i>
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE		\$ 250 <i>30</i>
4.	TO REMOVE & REINSTALL SENSORS		\$ 200 <i>50</i>
5.	ANTI RUST TREATMENT		\$ 200 <i>x</i>
6	<i>To change windscreen</i>	PARTS - 20%:	\$ 7,104
	<i>Adrian Lj</i>	SPECIAL NETT :	\$ 2,740
	<i>200</i>	LABOUR :	\$ 4,650
	<i>120</i>	TOTAL :	\$ 14,494 <i>14,694</i>
	<i>h/s 25/04/23</i>	8% GST :	\$ 1,159.52
	<i>04 Days.</i>	GRAND TOTAL :	\$ 15,653.52