

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: YQ 4039C

Policy No. _____

Claims No. MT/1219423-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA69492 Yr Regn: 2019, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i30 c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 622785 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UM MCS5 / CVK4 / 46258

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 20/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5/23 Lump Sum \$3000 confirmed by email (Red 1536.24, 33%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 4/5/23-typist

Report Format: TPLump Sum / L.B. / \$3000Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 20.04.2023MODEL: Hyundai IoniqVEHICLE NO.: SHA6949ZINSURANCE: YQ4039C
INCOMEMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Retainer LH	1		\$ 55.80
	Rear Bumper Clips	10	\$ 2.20	\$ 22.00
	Rear Wheel Cap LH	1		\$ 346.40
	Rear Door Outer Handle LH	1		\$ 108.40
	Rear Fender LH	1		\$ 1,768.30
	SUB TOTAL			\$ 2,760.30
	LESS 20%			\$ 552.06
	SPARE PARTS TOTAL			\$ 2,208.24
	Rear Fender (Petrol Only) LH	1		\$ 40.00
	Rear Door Apps Sticker LH	1		\$ 80.00
	S/NETT SUB	1		\$ 120.00
	LESS 10%			\$ 12.00
	S/NETT TOTAL			\$ 108.00
	SPARE PARTS TOTAL			\$ 2,316.24
	<u>Labour Charge</u>			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge - Rear Door LH etc			\$ 900.00
	R/I Reverse Sensors			\$ 120.00
	TOTAL LABOUR			\$ 2,220.00
	ESTIMATE TOTAL			\$ 4,536.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taiglin 97495749
WP 2/4/23 0430
4/5 Resurvey after repair
Taiglin & Consultants
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 20.04.2023 16:03

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5893799

JC NO305551919

OMER

COMFORT TRANSPORTATION PTE LTD

S 7010045

OMER NO 383 SIN MING DRIVE

ESS Singapore SINGAPORE 575717

65508755

(R) (O)

(P)

JUNT CARD NO.

REGN NO:

SHA6949Z

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 20.04.2023 14:00

YR OF MANU

30.04.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU146258

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 20.04.2023

ATURE: 3P 20.04.2023

NO


00010

LABOR CODE

PB

DESCRIPTION

LUMPSUM REPAIR-SHA6949Z-TP



VED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHA6949Z

LIMITS

Vehicle No.:

SHA6949Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard