



## COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 20.04.2023MODEL: Hyundai IoniqVEHICLE NO.: SHA6949ZINSURANCE: YQ4039C  
INCOMEMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Retainer LH	1		\$ 55.80
	Rear Bumper Clips	10	\$ 2.20	\$ 22.00
	Rear Wheel Cap LH	1		\$ 346.40
	Rear Door Outer Handle LH	1		\$ 108.40
	Rear Fender LH	1		\$ 1,768.30
	<b>SUB TOTAL</b>			\$ 2,760.30
	<b>LESS 20%</b>			\$ 552.06
	<b>SPARE PARTS TOTAL</b>			<b>\$ 2,208.24</b>
	Rear Fender (Petrol Only) LH	1		\$ 40.00
	Rear Door Apps Sticker LH	1		\$ 80.00
	<b>S/NETT SUB</b>	1		\$ 120.00
	<b>LESS 10%</b>			\$ 12.00
	<b>S/NETT TOTAL</b>			<b>\$ 108.00</b>
	<b>SPARE PARTS TOTAL</b>			<b>\$ 2,316.24</b>
	<u>Labour Charge</u>			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge - Rear Door LH etc			\$ 900.00
	R/I Reverse Sensors			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 2,220.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,536.24</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taiglin 97495749  
WP 2/4/23 0430  
4/5 Resurvey after repair  
Taiglin & Associates  
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Date/Time: 20.04.2023 16:03

Page : 1

am: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 5893799

JC NO305551919

OMER

COMFORT TRANSPORTATION PTE LTD

S 7010045

OMER NO 383 SIN MING DRIVE

ESS Singapore SINGAPORE 575717

65508755

(R) (O)

(P)

JUNT CARD NO.

REGN NO:

SHA6949Z

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

20.04.2023 14:00

DATE/TIME IN

YR OF MANU

30.04.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU146258

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 20.04.2023

ATURE: 3P 20.04.2023

NO


00010

LABOR CODE

PB

DESCRIPTION

LUMPSUM REPAIR-SHA6949Z-TP



VED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHA6949Z

LIMITS

Vehicle No.:

SHA6949Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard