

ASS. REC. BY: Taufik

REF:

INC NS/INC23004114/Tqp3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Lim TSVeh No: SMC 17669Yr Regn: 2017 DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Priusc.c. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 573649

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STDICKSF4X03090481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 20/4/25Survey held at Wong Tze Yee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$2400, 3 days. (Red \$2165.33, 47%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format: TPLump Sum / LS / 2400

## COMFORTDELGRO ENGINEERING PTE LTD

SAS-KLV

## REPAIR ESTIMATE

DATE: 20.04.2023

SKM8615A

INSURANCE: INCOME (L5)

MODEL: Toyota Prius G4A

MVA: LIM T S

VEHICLE NO.: SHC1766G

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Trunk Outer Garnish	1		\$1,054.71 <i>Re</i>
	Rear Trunk Lid Logo (Prius)	1		\$62.14 <i>net</i>
	Rear Trunk Lid Logo (Hybrid)	1		\$62.14 <i>net</i>
	Rear Trunk Lid Logo (Toyota Star)	1		\$81.43 <i>x</i>
	Rear Bumper	1		\$551.89 <i>de</i>
	Rear Bumper Re-Inforcement	1		\$378.32 <i>bf</i>
	Rear Bumper Lower Cover-Black	1		\$654.96 <i>de</i>
	Rear Bumper Under Floor Cover	1		\$425.25 <i>mis</i>
	Rear Bumper Reflector RH / LH	2	\$55.00	\$110.00 <i>x</i>
	Rear Bumper Side Brkt RH / LH	2	\$112.70	\$225.40 <i>x</i>
	Rear Bumper Clips	10	\$2.20	\$22.00 <i>net</i>
	Rear Bumper Tow Cover	1		\$82.70 <i>mis</i>
	<b>SUB TOTAL</b>			\$3,710.94
	<b>LESS 25%</b>			\$927.74
	<b>DISCOUNTED TOTAL</b>			<b>\$2,783.20</b>
	Reverse Sensor	1		\$135.70 <i>net</i>
	Rear Trunk ComfortDelGro	1		\$30.00 <i>net</i>
	Rear Trunk 65521111	1		\$30.00 <i>net</i>
	Rear Trunk ZIG APPS	1		\$40.00 <i>net</i>
	<b>SUB S/NETT</b>			\$235.70
	<b>LESS 10%</b>			\$23.57
	<b>S/NETT TOTAL</b>			<b>\$212.13</b>
	Rear Bumper Mat	1		\$50.00 <i>net</i>
	<b>TOTAL SPARE PARTS</b>			<b>\$3,045.33</b>
	<b>Labour Charge</b>			
	Panel Beating			\$800.00 <i>525</i>
	Spray Painting Charge			\$600.00 <i>500</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>30</i>
	<b>TOTAL LABOUR</b>			<b>\$1,520.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$4,565.33</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Toyota Prius



Date/Time: 20.04.2023 14:55

Page : 1

Team: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 5893786

JC NO305551915

CUSTOMER  MS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO. <b>SHC1766G</b>	MILEAGE
	MAKE <b>TOYOTA</b>	FUEL E.....1/2.....F
	MODEL <b>PRIUS HYBRID(G4A20.04.2023 13:05</b>	DATE/TIME IN
	YR OF MANU. <b>19.12.2019</b>	TARGET DATE
	CHASSIS CODE <b>JTDKB3FUX03090481</b>	COMPLETION DATE/TIME:

COUNT CARD NO.

Accident Date: 20.04.2023

NATURE: 3P 20.04.2023


LABOR CODE  
PB

JOB DESCRIPTION

*LS*  
*Income*

DESCRIPTION  
LUMPSUM REPAIR-SHC1766G-TP

*SKM*  
*8615A*



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHC1766G

LIMITS

Vehicle No.: SHC1766G

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard