

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowok@gmail.com



Veron.

DATE : 19.04.2023

TO : INCOME MOTOR CLAIMS DEPTS
VEHICLE NO : SLQ3589S
MODEL : MAZDA 3
DATE OF ACCIDENT : 19.04.2023
TIME OF ACCIDENT : 10:25 HOURS

JM6BN22A8H0157493

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 958.00	\$ 958.00
2	FRONT BUMPER SIDE RETAINER <i>Rehnd</i>	2	\$ 27.30	\$ 54.60
3	HEADLAMP RH (HID) <i>Rehnd</i>	1	\$ 1,889.00	\$ 1,889.00
4	FRONT FENDER RH <i>Distahnd</i>	1	\$ 383.20	\$ 383.20
5	FRONT FENDER INNER SPONGE RH <i>Rehnd</i>	1	\$ 94.60	\$ 94.60
6	FRONT FENDER COWLING RH <i>Rehnd</i>	1	\$ 114.30	\$ 114.30
7	FRONT DOOR PILLAR RH (OUTER) <i>Rehnd</i>	1	\$ 1,070.60	\$ 1,070.60
8	FRONT DOOR RH <i>Rehnd</i>	1	\$ 1,796.40	\$ 1,796.40
9	FRONT DOOR VIEW MIRROR RH <i>Rehnd</i>	1	\$ 1,355.60	\$ 1,355.60
10	FRONT DOOR HINGE RH <i>Rehnd</i>	2	\$ 51.70	\$ 103.40
11	FRONT DOOR CHECKER RH <i>Rehnd</i>	1	\$ 126.40	\$ 126.40
12	FRONT DOOR SPEAKER RH <i>Rehnd</i>	1	\$ 398.60	\$ 398.60
13	FRONT DOOR INNER TRIM RH <i>Rehnd</i>	1	\$ 1,216.70	\$ 1,216.70
14	FRONT DOOR INNER LOCK RH <i>Rehnd</i>	1	\$ 367.10	\$ 367.10
15	FRONT DOOR LOCK CATCHER RH <i>Rehnd</i>	1	\$ 28.20	\$ 28.20
16	FRONT DOOR WEATHER STRIP RH <i>Rehnd</i>	1	\$ 114.70	\$ 114.70
17	FRONT DOOR OUTER STRIP RH <i>Rehnd</i>	1	\$ 142.60	\$ 142.60
18	FRONT DOOR POWER WINDOW MOTOR RH <i>Rehnd</i>	1	\$ 379.40	\$ 379.40
19	FRONT STEERING RACK AND PINION <i>Rehnd</i>	1	\$ 1,867.00	\$ 1,867.00
20	FRONT LOWER ARM RH <i>Rehnd</i>	1	\$ 289.30	\$ 289.30
21	FRONT SHOCK ABSORBER RH <i>Rehnd</i>	1	\$ 298.60	\$ 298.60

1275
466
+

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ3589S**
 MODEL : **MAZDA 3**
 DATE OF ACCIDENT : 19.04.2023
 TIME OF ACCIDENT : 10:25 HOURS

22	FRONT LINKAGE RH <i>new</i>	1	\$ 101.20	\$ 101.20	x
23	FRONT WHEEL HUP RH <i>new</i>	1	\$ 480.40	\$ 480.40	x
24	FRONT WHEEL HUP BEARING RH <i>new</i>	1	\$ 299.50	\$ 299.50	x
25	FRONT KNUCKLE ARM RH <i>new</i>	1	\$ 631.10	\$ 631.10	x
26	FRONT ABS SENSOR RH <i>new</i>	1	\$ 296.70	\$ 296.70	x

4986.80
3989.44

TOTAL PRICE \$ 14,857.20
 LESS 20% \$ 2,971.44
SUB TOTAL PRICE \$ 11,885.76

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT FENDER COWLING CLIP RH <i>new</i>	1	\$ 50.00	\$ 50.00	30
2	FRONT WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
3	FRONT WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	+
4	FRONT DOOR SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	+
5	FRONT DOOR INNER TRIM <i>new</i>	1	\$ 80.00	\$ 80.00	+
6	DASHBOARD CLIP <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	FRONT DOOR PILLAR (OUTER) SEALANT RH <i>new</i>	1	\$ 120.00	\$ 120.00	+
8	FRONT PILLAR INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
9	FRONT WIPER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
10	WHEEL TYRE RH <i>new</i>	1	\$ 800.00	\$ 800.00	+
11	WHEEL RIM RH <i>new</i>	1	\$ 1,800.00	\$ 1,800.00	580.
12	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	x

610

TOTAL \$ 3,340.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800 650 20/6/23 adrian
3	TUFF COAT	\$ 250.00	80
4	WIRING CHECK	\$ 250.00	30

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ3589S**
 MODEL : **MAZDA 3**
 DATE OF ACCIDENT : 19.04.2023
 TIME OF ACCIDENT : 10:25 HOURS

5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	X
6	REFOCUS HEADLAMP BEAM	\$ 60.00	X
7	REMOVE AND REFIX FRONT DASHBOARD	\$ 1,200.00	X
8	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	60.
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	200
10	REMOVE AND REFIX STEERING RACK AND PINION	\$ 350.00	X
11	FOUR WHEEL ALIGNMENT	\$ 120.00	80.
12	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
13	RESET ABS LIGHT	\$ 350.00	X
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$7,160.00

TOTAL PARTS COST : \$ 15,225.76
 TOTAL LABOUR COST : \$ 7,160.00
 TOTAL REPAIR COST : \$ 22,385.76

Adrian Ly
 L/S 21/04/23.
 06 days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 624544
 L/S 5K

1650