

ASS. REC. BY:

REF:

105/ 23004119/Kny3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

215 711P @ 630d Calw 7/5/23 (red, \$28960, 82%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S + RS. SI

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 18 / 04 / 2023

ESTIMATE COSTS OF REPAIR

Ms Lau Yan Lin, Sabrina

C/o 160 Sin Ming Drive

#05-09 Sin Ming Auto City

Singapore 575722

*Not Notified
11 Day @ 6300/hr
Paying After Repair
5 days*

Dear Sir / Madam ,

Vehicle no. : SLP 7102 S - Audi A1 SB 1.0 TFSI (PI)

Accident date : 17 / 04 / 2023

Quantity	Descriptions	Amount (S\$)
1	1 pc front bumper	\$ 2,400.00 X
2	1 pc o/s front bumper side retainer	\$ 180.00 X
3	1 pc o/s side mirror	\$ 900.00 ✓
4	1 pc o/s front door	\$ 2,100.00 ✓
5	2 pcs front door hinge	\$ 180.00 X
6	1 pc o/s front door weather-strip	\$ 300.00 X
7	1 pc o/s front door inner trim	\$ 1,800.00 X
8	1 pc o/s front door inner lock	\$ 600.00 X
9	1 pc o/s front door channel rail	\$ 400.00 X
10	1 pc o/s front door regulator gear	\$ 800.00 X
11	1 pc o/s front door regulator motor	\$ 1,200.00 X
12	1 pc o/s front door glass outer molding	\$ 380.00 X
13	1 pc o/s front fender 912	\$ 920.00 ✓
14	1 pc o/s front fender inner garnish	\$ 270.00 X
15	1 pc o/s rear door	\$ 2,200.00 X
16	2 pcs rear door hinge	\$ 180.00 X
17	1 pc o/s front shock absorber 405	\$ 520.00 ✓
18	1 pc o/s front knuckle arm 672	\$ 950.00 ✓
19	1 pc o/s front knuckle arm bearing 485	\$ 570.00 ✓
20	1 pc o/s front lower arm	\$ 480.00 ✓
21	1 pc steering rack & pinion	\$ 4,800.00 X
		\$ 22,130.00
22	1 pc o/s front wheel tyre	\$ 780.00 sn X
23	1 pc o/s front wheel rim R? 1015	\$ 1,400.00 sn ✓
Balance C/FD		\$ 24,310.00

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SLP 7102 S)

\$ 24,310.00

Labour charges

\$ 4,800.00

To putty and spray painting

\$ 2,500.00

Re-seal anti rust

\$ 200.00

To check, replace, repair wiring, reset fault code

\$ 280.00

To check wheel alignment

\$ 120.00

To transfer door

\$ 250.00

Remove and refix cushion seat, garnish, carpet, roof top, etc

\$ 2,800.00

\$ 35,260.00

Add : 8% GST

\$ 2,820.80

Grand total

\$ 38,080.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: