

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC3371X

SHC3372X

19.04.2023

MAKE REG 21.04.2016

MODEL I-40

CHIANG/

Income

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	LH/SIDE WING MIRROR			\$670.00
1	ROCKER GRANISH LH			\$732.80
	SUB TOTAL			\$1,402.80
	20.00%			\$280.56
				\$1,122.24
1	REAR DOOR COMFORT APP STICKER			\$80.00
				\$80.00
	Labour Charge			
	Panel Beating		240	\$450.00
	Spray Painting Charge		776	\$700.00
	TOTAL LABOUR			\$1,150.00
	ESTIMATE TOTAL			\$2,352.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tan Jun 97495749
 WP 20/4/23 @ 4pm
 4/5 Resurvey after repair
 Tan Jun 21/4/23 on
 01 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: