



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23004123/Twy3e2 Date: 03/05/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	PA 8504R	Veh. Inspected	SMW 9523Z	
Policy No.	SD22V03497 /VBZ/R03	Coverage (\$)	0.00	
Claim No.	AVS22/2027	Excess (\$)	0.00	
Assign From	ESTHER CHEAH	Assign Date	19/04/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CHR HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	ZYX102110294	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	TOURADOR	6 mm	
L/H Front Tyre	215/60 R17	TOURADOR	6 mm	
R/H Rear Tyre	215/60 R17	TOURADOR	6 mm	
L/H Rear Tyre	215/60 R17	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	22/07/2022	Inspection Date	25/04/2023	
Survey held at	SA AUTOMOBILE PTE LTD 39 WOODLANDS CLOSE #02-43 MEGA@WOODLANDS SINGAPORE 737856			
5a. Remarks				
A)REGISTRATION DATE: 18 MAY 2018 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		